

Priority Areas Lead Testing and Corrective Actions NOVEMBER 2014  
NAVAL STATION MAYPORT Child Development Center Building 1960

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)		Recommended Level = 20ppb	
Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb) (See Note 2)							First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	
<b>SAMPLING DATE</b>			<b>10/11/2014</b>			<b>mm/dd/yyyy</b>	<b>11/5/2014</b>	<b>11/5/2014</b>		<b>mm/dd/yyyy</b>	
<b>RESULTS DATE</b>			<b>10/17/2014</b>			<b>mm/dd/yyyy</b>	<b>11/6/2014</b>	<b>11/6/2014</b>		<b>mm/dd/yyyy</b>	
DRINKING	MYP-1960-HALL-WFC-A-FD (BLDG 1960-1)	Hallway near lobby desk - Low fountain located near the entrance	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MYP-1960-HALL-WFC-B-FD (BLDG 1960-2)	Hallway near lobby desk - Low fountain	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MYP-1960-HALL-WFC-C-FD (BLDG 1960-3)	Hallway near lobby desk - High fountain	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MYP-1960-RM111-PLAY-WFB-FD (BLDG 1960-11)	Outside Room 111 - Bubbler fountain outside	6.4	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MYP-1960-RM116-PLAY-WFB-FD (BLDG 1960-24)	Outside Room 116 - This fountain is not used by the children.	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MYP-1960-RM131-PLAY-WFB-FD (BLDG 1960-52)	Outside of room 131 - Playground	4.3	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	MYP-1960-RM108-K-K-A-FD (BLDG 1960-4)	Kitchen - Triple stainless steel sink used to wash dishes	1.3	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	MYP-1960-RM108-K-K-B-FD (BLDG 1960-5)	Kitchen - Triple stainless steel sink used to wash dishes	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	MYP-1960-RM108-K-HHW-FD (BLDG 1960-6)	Kitchen - Stainless steel handwashing sink	3.6	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	MYP-1960-RM108-K-K-C-FD (BLDG 1960-7)	Kitchen - Double sink used for food preparation	2.6	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM111-RM-HHW-FD (BLDG 1960-8)	Toddler Room - Stainless steel sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM111-RM-LHW-A-FD (BLDG 1960-9)	Toddler Room - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM111-RM-LHW-B-FD (BLDG 1960-10)	Toddler Room - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM112-RM-HHW-FD (BLDG 1960-12)	Toddler Room 2 - Stainless steel sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM112-RM-LHW-A-FD (BLDG 1960-13)	Toddler Room 2 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM112-RM-LHW-B-FD (BLDG 1960-14)	Toddler Room 2 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM113-RM-HHW-FD (BLDG 1960-15)	Toddler Room 3 - Stainless steel sink	9	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM113-RM-LHW-A-FD (BLDG 1960-16)	Toddler Room 3 - Child's bathroom sink	4.3	NO	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions NOVEMBER 2014  
NAVAL STATION MAYPORT Child Development Center Building 1960

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 20ppb							Recommended Level = 20ppb	
			First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb) (See Note 2)	Description	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			10/11/2014			mm/dd/yyyy	11/5/2014	11/5/2014		mm/dd/yyyy	
RESULTS DATE			10/17/2014			mm/dd/yyyy	11/6/2014	11/6/2014		mm/dd/yyyy	
WASHING	MYP-1960-RM113-RM-LHW-B FD (BLDG 1960-17)	Toddler Room 3 Child's bathroom sink	21	YES	11/4/2014	N/A	17	1.6	Routine Control Measures Only - Aerator Cleaned	N/A	N/A
WASHING	MYP-1960-RM114-RM-HHW- FD (BLDG 1960-18)	Toddler Room 4 - Stainless steel sink	2.9	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM114-RM-LHW-A FD (BLDG 1960-19)	Toddler Room 4 - Child's bathroom sink	11	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM114-RM-LHW-B FD (BLDG 1960-20)	Toddler Room 4 - Child's bathroom sink	9.1	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM116-RM-LHW-A FD (BLDG 1960-21)	Preschool 3 - End of Hall, childs bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM116-RM-LHW-B FD (BLDG 1960-22)	Preschool 3 - End of Hall, childs bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM116-RM-HHW- FD (BLDG 1960-23)	Preschool 3 - End of Hall, stainless steel sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM117-RM-HHW- FD (BLDG 1960-25)	Preschool 2 - Stainless steel sink	2.1	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM117-RM-LHW-A FD (BLDG 1960-26)	Preschool 2 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM117-RM-LHW-B FD (BLDG 1960-27)	Preschool 2 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM118-RM-LHW-A FD (BLDG 1960-28)	Preschool 1 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM118-RM-LHW-B FD (BLDG 1960-29)	Preschool 1 - Child's bathroom sink	3	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM118-RM-HHW- FD (BLDG 1960-30)	Preschool 1 - Stainless steel sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM120-BATH- HHW-A-FD (BLDG 1960-31)	Women's Bathroom - Restroom sink on left	1.9	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM120-BATH- HHW-B-FD (BLDG 1960-32)	Women's Bathroom - Restroom sink on right	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM120-BATH- HHW-C (BLDG 1960-33)	Women's Bathroom - Handicap bathroom	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM121-BATH- HHW-A-FD (BLDG 1960-34)	Men's Bathroom - Handicap bathroom	3	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM121-BATH- HHW-B-FD (BLDG 1960-35)	Men's Bathroom - Restroom sink on left	2.1	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM121-BATH- HHW-C-FD (BLDG 1960-36)	Men's Bathroom - Restroom sink on right	1.4	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM122-RM-HHW- A-FD (BLDG 1960-37)	Infant 1 - Sink on left	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions NOVEMBER 2014  
NAVAL STATION MAYPORT Child Development Center Building 1960

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)		Recommended Level = 20ppb	
Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb) (See Note 2)							mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy
<b>SAMPLING DATE</b>			<b>10/11/2014</b>			<b>mm/dd/yyyy</b>	<b>11/5/2014</b>	<b>11/5/2014</b>		<b>mm/dd/yyyy</b>	
<b>RESULTS DATE</b>			<b>10/17/2014</b>			<b>mm/dd/yyyy</b>	<b>11/6/2014</b>	<b>11/6/2014</b>		<b>mm/dd/yyyy</b>	
WASHING	MYP-1960-RM122-RM-HHW-B-FD (BLDG 1960-38)	Infant 1 - Sink on right	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM129-RM-HHW-A-FD (BLDG 1960-39)	Infant 2 - Sink on left	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM129-RM-HHW-B-FD (BLDG 1960-40)	Infant 2 - Sink on right	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM130-LOUNGE-K (BLDG 1960-41)	Staff Breakroom - Stainless steel sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM128-RM-HHW-A-FD (BLDG 1960-42)	Infant 4 - Sink on left	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM128-RM-HHW-B-FD (BLDG 1960-43)	Infant 4 - Sink on right	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM123-RM-HHW-A-FD (BLDG 1960-44)	Infant 3 - Sink on left	2.3	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM123-RM-HHW-B-FD (BLDG 1960-45)	Infant 3 - Sink on right	2	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM127-RM-LHW-A-FD (BLDG 1960-46)	Pre-toddler 3 - Across from room 124, child's bathroom sink	19	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM127-RM-LHW-B-FD (BLDG 1960-47)	Pre-toddler 3 - Across from room 124, child's bathroom sink	5.4	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM127-RM-HHW-FD (BLDG 1960-48)	Pre-toddler 3 - Across from room 124. stainless steel sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM125-RM-LHW-A-FD (BLDG 1960-49)	Pre-toddler 3 - Child's bathroom sink	1.8	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM125-RM-LHW-B-FD (BLDG 1960-50)	Pre-toddler 1 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM125-RM-HHW-FD (BLDG 1960-51)	Pre-toddler 1 - Stainless steel sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM126-RM-LHW-A-FD (BLDG 1960-53)	Pre-toddler 2 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM126-RM-LHW-B-FD (BLDG 1960-54)	Pre-toddler 2 - Child's bathroom sink	1.6	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM126-RM-HHW-FD (BLDG 1960-55)	Pre-toddler 2 - Stainless steel sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Notes:

<sup>1</sup> Affected outlets were immediately secured after receiving verbal communication from the lab on results exceeding the recommended level of 20ppb.

<sup>2</sup> Post-remediation sampling was initially conducted on 11/5/2014. Additional routine control measures such as aerator cleaning were implemented and final results below recommended level of 20ppb for sample collected on 11/5/2014 are shown on the table.

Priority Areas Lead Testing and Corrective Actions NOVEMBER 2014  
 NAVAL STATION MAYPORT Child Development Center Building 1960

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS	RE-SAMPLING RESULTS			POST REMEDIATION RESULTS
	Recommended Level = 20ppb				
	First Draw (ppb)	Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb)
Total Drinking	6	0	0	0	0
Total Drinking > 20 ppb	0	0	0	0	0
Total Cook/Brush	4	0	0	0	0
Total Cook/Brush > 20 ppb	0	0	0	0	0
Total Washing	45	0	1	1	0
Total Washing > 20 ppb	1	0	0	0	0
Total Samples	55	0	1	1	0
Total Samples > 20 ppb	1	0	0	0	0