PRIORITY AREAS LEAD TESTING AND CORRECTIVE ACTIONS (OCTOBER 2014)
JBPHH HICKAM MAIN CHILD DEVELOPMENT CENTER
BUILDING 1597H, 1598H, 1599H

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION				INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS		CORRECTIVE ACTIONS	POST-REMEDIATION SAMPLING		COMMENTS
				Recommended Level = 20 ppb						Recommended Level = 20 ppb		
SAMPLE ID	FLOOR PLAN NO.	ROOM NO.	Outlet Description	First Draw (ppb)	Retest Required?	Date Fixture Secured?	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb)	Retest required?	
SAMPLING DATE				10/18/2014			11/21/2014			1/7/2015		
RESULTS DATE				11/6/2014; 11/19/2014			12/3/2014			2/6/2015		
JB-1597H-1-B-HHW	1	Bath	Adult Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-2-Staff-HHW	2	Staff Rm	Adult Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-3-A9-LHW	3	A9	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-4-A9-LHW	4	A9	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-5-A9-LHW	5	A9	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-6-A9-LHW	6	A9	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-7-A9-WFB	7	Exterior	Water Fountain	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-8-A9-K	8	Kitchen	Kitchen Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-9-A9-K	9	Kitchen	Kitchen Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-10-A9-K	10	Kitchen	Kitchen Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-11-A9-K	11	Kitchen	Kitchen Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-14-B2-LHW	14	B2	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-15-B2-LHW	15	B2	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-16-B-HHW	16	Bath	Adult Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-17-B1-LHW	17	B1	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-18-B1-LHW	18	B1	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-19-B4-LHW	19	B4	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-20-B4-LHW	20	B4	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-21-B3-LHW	21	B3	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-22-B3-LHW	22	B3	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-23-B-HHW	23	Bath	Adult Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-24-B-LHW	24	Bath	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-25-B-LHW	25	Bath	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-27-C1-LHW	27	C1	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-28-C1-LHW	28	C1	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-29-C4-LHW	29	C4	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-30-C4-LHW	30	C4	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-31-C3-LHW	31	C3	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-32-C3-LHW	32	C3	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-33-B-HHW	33	B	Adult Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-34-B-HHW	34	B	Adult Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-35-C2-LHW	35	C2	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-36-C2-LHW	36	C2	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1597H-37-A9-K	37	Kitchen	Kitchen Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1598H-2-D2-LHW	2	D2	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1598H-3-D2-LHW	3	D2	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1598H-4-B-LHW	4	Bath	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1598H-5-D1-LHW	5	D1	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1598H-6-D1-LHW	6	D1	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1598H-7-B-HHW	7	Bath	Adult Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	

PRIORITY AREAS LEAD TESTING AND CORRECTIVE ACTIONS (OCTOBER 2014)
JBPHH HICKAM MAIN CHILD DEVELOPMENT CENTER
BUILDING 1597H, 1598H, 1599H

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION				INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS		CORRECTIVE ACTIONS	POST-REMEDIATION SAMPLING		COMMENTS
				Recommended Level = 20 ppb						Recommended Level = 20 ppb		
SAMPLE ID	FLOOR PLAN NO.	ROOM NO.	Outlet Description	First Draw (ppb)	Retest Required?	Date Fixture Secured?	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb)	Retest required?	
SAMPLING DATE				10/18/2014			11/21/2014			1/7/2015		
RESULTS DATE				11/6/2014; 11/19/2014			12/3/2014			2/6/2015		
JB-1598H-9-D4-LHW	9	D4	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1598H-10-D4-LHW	10	D4	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1598H-11-B-LHW	11	Bath	Toddler Sink	12.2	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1598H-12-D3-LHW	12	D3	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1598H-13-D3-LHW	13	D3	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1599H-1-EXT-HB	1	Exterior	Hose Bib	25.5	Yes	11/20/2014	17.9	<5	Fixture replaced	8.08	No	Remediation completed
JB-1599H-2-E2-WFCOMB	2	E2	Toddler Water Fountain	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1599H-3-E2-HWCOMB	3	E2	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1599H-4-E2-LHW	4	E2	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1599H-5-E2-LHW	5	E2	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1599H-6-E1-LHW	6	E1	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1599H-7-E1-LHW	7	E1	Toddler Sink	6.28	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1599H-8-E1-HWCOMB	8	E1	Toddler Sink	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1599H-9-E1-WFCOMB	9	E1	Toddler Water Fountain	<5	No	N/A	N/A	N/A	N/A	N/A	N/A	
JB-1599H-10-EXT-HB	10	Exterior	Hose Bib	9.98	No	N/A	N/A	N/A	N/A	N/A	N/A	