

Priority Areas Lead Testing and Corrective Actions
CFAY Ikego Detachment Child Development Center Bldg 673 (Nov 2017)

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION				INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY	SAMPLE ID	Outlet Description	Comments	Lead Screening Level of 20ppb							Recommended Level = 20ppb	
				First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE				9/30/2017			N/A	N/A	N/A		N/A	
RESULTS DATE				11/6/2017			N/A	N/A	N/A		N/A	
DRINKING	IKE673B012	Bubbler		7.1	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	IKE673B022	Bubbler		non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	IKE673B027	Bubbler		non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	IKE673B032	Bubbler		1.4	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	IKE673B062	Bubbler		1.4	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	IKE673C045	Cooler		non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	IKE673C046	Cooler		non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	IKE673F050	Faucet		4.6	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	IKE673F051	Faucet		non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	IKE673F052	Faucet		1.1	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	IKE673F053	Faucet		non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	IKE673F054	Faucet		non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	IKE673F055	Faucet		non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	IKE673F056	Faucet		3	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F001	Faucet		non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F002	Faucet		0.62	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F003	Faucet		1.2	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F004	Faucet		1	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F005	Faucet		0.81	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F006	Faucet		non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F008	Faucet		1.6	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F009	Faucet		2.3	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F010	Faucet		1	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F011	Faucet		6.1	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F013	Faucet		0.57	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F014	Faucet		0.53	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F015	Faucet		0.59	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F016	Faucet		1.1	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F018	Faucet		2.1	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F019	Faucet		2.2	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F020	Faucet		2.3	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F021	Faucet		3.5	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F023	Faucet		1.4	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F024	Faucet		1.1	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F025	Faucet		1.6	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F026	Faucet		2	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F028	Faucet		4	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F029	Faucet		3.2	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F030	Faucet		4.2	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F031	Faucet		4.4	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F033	Faucet		non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F034	Faucet		non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions
CFAY Ikego Detachment Child Development Center Bldg 673 (Nov 2017)

SAMPLING LOCATION DESCRIPTION				INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY	SAMPLE ID	Outlet Description	Comments	Lead Screening Level of 20ppb							Recommended Level = 20ppb	
				First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE				9/30/2017			N/A	N/A	N/A		N/A	
RESULTS DATE				11/6/2017			N/A	N/A	N/A		N/A	
WASHING	IKE673F035	Faucet		0.54	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F036	Faucet		non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F037	Faucet		non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F038	Faucet		1.1	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F039	Faucet		1.2	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F040	Faucet		non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F042	Faucet		2.2	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F043	Faucet		3.4	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F044	Faucet		non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	IKE673F047	Faucet		1.3	NO	N/A	N/A	N/A	N/A		N/A	N/A

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS		RE-SAMPLING RESULTS		POST REMEDIATION RESULTS
	Lead Screening Level of 20ppb				
	First Draw (ppb)	Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	
Total Drinking	7	0	0	0	0
Total Drinking > 20 ppb	0	0	0	0	0
Total Cook	7	0	0	0	0
Total Cook > 20 ppb	0	0	0	0	0
Total Washing	38	0	0	0	0
Total Washing > 20 ppb	0	0	0	0	0
Total Samples	52	0	0	0	0
Total Samples > 20 ppb	0	0	0	0	0