

Priority Areas Lead Testing and Corrective Actions  
CFAY Ikego Detachment Youth Center  
Bldg 692 (Oct 2017)

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION				INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS Description	POST REMEDIATION SAMPLING Recommended Level = 20ppb	
CATEGORY	SAMPLE ID	Outlet Description	Comments	First Draw (ppb)	Retest required?	Date Fixture Secured?	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)		First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
<b>SAMPLING DATE</b>				9/30/2017			N/A	N/A	N/A		N/A	
<b>RESULTS DATE</b>				10/26/2017			N/A	N/A	N/A		N/A	
DRINKING	IKE692C001	Cooler		non-detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	
COOKING	IKE692F002	Faucet		non-detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	
WASHING	IKE692F003	Faucet		0.9	NO	N/A	N/A	N/A	N/A	N/A	N/A	
WASHING	IKE692F004	Faucet		non-detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	
WASHING	IKE692F005	Faucet		0.78	NO	N/A	N/A	N/A	N/A	N/A	N/A	

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS	RE-SAMPLING RESULTS			POST REMEDIATION RESULTS
	First Draw (ppb)	Lead Screening Level of 20ppb			First Draw (ppb)
		Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	
<b>Total Drinking</b>	1	0	0	0	0
<b>Total Drinking &gt; 20 ppb</b>	0	0	0	0	0
<b>Total Cook</b>	1	0	0	0	0
<b>Total Cook &gt; 20 ppb</b>	0	0	0	0	0
<b>Total Washing</b>	3	0	0	0	0
<b>Total Washing &gt; 20 ppb</b>	0	0	0	0	0
<b>Total Samples</b>	5	0	0	0	0
<b>Total Samples &gt; 20 ppb</b>	0	0	0	0	0