

**Priority Areas Lead Testing and Corrective Action
Ikego Elementary School - bldg 824 (FULL RESULTS AS OF 9 NOV 17)**

SAMPLE LOCATION DESCRIPTION			INITIAL FULL BUILDING SAMPLING RESULTS			SECOND FULL BUILDING SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Recommended Level = 20ppb						Description	Recommended Level = 20ppb	
						First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush Collected 30 seconds after First Draw Sampling (ppb)		First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			4/15, 4/19-21/2017			7/25-28/2017			6/15/2017	6/16/2017	6/16/2017		8/4/2017 & 9/19-21/2017	
RESULTS DATE			5/17/2017			8/29/2017			7/20/2017	7/20/2017	7/20/2017		8/28/2017 & 10/26/2017	
Drinking	IKE824B015	Bubbler	0.7	NO	4/10/2017	non-detect	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B021	Bubbler	7.9	NO	4/10/2017	non-detect	NA	4/10/2017	-	-	-		-	-
Drinking	IKE824B022	Bubbler	27	YES	4/10/2017	NA	NA	4/10/2017	NA	11	2.1	Replaced bubbler	6.5	2.1
Drinking	IKE824B023	Bubbler	6.0	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	1.4	-
Drinking	IKE824B027	Bubbler	4.6	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	5.8	-
Drinking	IKE824B017	Bubbler	5.3	NO	4/10/2017	non-detect	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B044	Bubbler	9.5	NO	4/10/2017	0.53	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B045	Bubbler	6.0	NO	4/10/2017	1.1	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B046	Bubbler	5.7	NO	4/10/2017	1.6	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B047	Bubbler	9.9	NO	4/10/2017	non-detect	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B048	Bubbler	3.8	NO	4/10/2017	non-detect	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B014	Bubbler	2.8	NO	4/10/2017	0.87	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B049	Bubbler	3.8	NO	4/10/2017	non-detect	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B032	Bubbler	6.6	NO	4/10/2017	non-detect	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B035	Bubbler	11	NO	4/10/2017	0.5	NO	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	0.68	-
Drinking	IKE824B038	Bubbler	7.6	NO	4/10/2017	1.1	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B050	Bubbler	0.75	NO	4/10/2017	non-detect	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B051	Bubbler	2.2	NO	4/10/2017	0.66	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B041	Bubbler	3.5	NO	4/10/2017	4.5	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B053	Bubbler	8.2	NO	4/10/2017	2.9	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B054	Bubbler	2.1	NO	4/10/2017	non-detect	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B087	Bubbler	34	YES	4/10/2017	NA	NA	4/10/2017	NA	29	8.9	Replaced bubbler	7.2	0.88
Drinking	IKE824B088	Bubbler	79	YES	4/10/2017	NA	NA	4/10/2017	NA	40	11	Replaced bubbler	9.4	1.7
Drinking	IKE824B089	Bubbler	88	YES	4/10/2017	NA	NA	4/10/2017	NA	28	12	Replaced bubbler	8.2	3.3
Drinking	IKE824B090	Bubbler	30	YES	4/10/2017	NA	NA	4/10/2017	NA	10	3.8	Replaced bubbler	6.8	3
Drinking	IKE824B091	Bubbler	24	YES	4/10/2017	NA	NA	4/10/2017	NA	7.1	14	Replaced bubbler	4.3	1.3
Drinking	IKE824B094	Bubbler	13	NO	4/10/2017	1.7	NO	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	4.6	-
Drinking	IKE824B081	Bubbler	19	NO	4/10/2017	2.0	NO	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	3.1	1.4
Drinking	IKE824B077	Bubbler	8.5	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	2.7	-
Drinking	IKE824B078	Bubbler	9.3	NO	4/10/2017	1.2	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B079	Bubbler	6.9	NO	4/10/2017	1.7	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B080	Bubbler	1.9	NO	4/10/2017	2.0	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B082	Bubbler	2.8	NO	4/10/2017	0.83	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B083	Bubbler	4.6	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	3.5	-
Drinking	IKE824B093	Bubbler	5.7	NO	4/10/2017	1.2	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B084	Bubbler	5.1	NO	4/10/2017	5.3	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B085	Bubbler	2.1	NO	4/10/2017	0.77	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B139	Bubbler	2.1	NO	4/10/2017	1.7	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B140	Bubbler	5.7	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	7.2	-
Drinking	IKE824B141	Bubbler	17	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	7.2	-
Drinking	IKE824B142	Bubbler	3.4	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	4	-
Drinking	IKE824B135	Bubbler	5.5	NO	4/10/2017	3.9	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B126	Bubbler	6.7	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	1.8	-

SAMPLE LOCATION DESCRIPTION			INITIAL FULL BUILDING SAMPLING RESULTS			SECOND FULL BUILDING SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 20ppb									Description	Recommended Level = 20ppb	
			First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush Collected 30 seconds after First Draw Sampling (ppb)		First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
Drinking	IKE824B132	Bubbler	3.5	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	2.1	-
Drinking	IKE824B127	Bubbler	9.0	NO	4/10/2017	3.8	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B133	Bubbler	4.7	NO	4/10/2017	5.9	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B128	Bubbler	9.3	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	2	-
Drinking	IKE824B134	Bubbler	7.0	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	7.1	-
Drinking	IKE824B129	Bubbler	6.4	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	2.5	-
Drinking	IKE824B130	Bubbler	2.2	NO	4/10/2017	1.6	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B131	Bubbler	6.8	NO	4/10/2017	2.3	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824B136	Bubbler	6.3	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	2.3	-
Drinking	IKE824B137	Bubbler	25	YES	4/10/2017	NA	NA	4/10/2017	NA	14	2.2	Replaced bubbler	7.5	1.4
Drinking	IKE824C1	Cooler	0.74	NO	4/10/2017	2.4	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824C2	Cooler	3.4	NO	4/10/2017	1.3	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824C3	Cooler	0.63	NO	4/10/2017	0.9	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824C4	Cooler	5.7	NO	4/10/2017	0.86	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824C5	Cooler	0.67	NO	4/10/2017	1.7	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824C6	Cooler	1.2	NO	4/10/2017	2.5	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824C66	Cooler	1.4	NO	4/10/2017	2.3	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824C67	Cooler	0.61	NO	4/10/2017	2.0	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824C68	Cooler	non-detect	NO	4/10/2017	0.73	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824C69	Cooler	non-detect	NO	4/10/2017	1.3	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824C101	Cooler	32	YES	4/10/2017	NA	NA	4/10/2017	0.76	5.4	5.8	Replaced cooler	non-detect	non-detect
Drinking	IKE824C102	Cooler	10	NO	4/10/2017	7.0	NO	4/10/2017	-	-	-	Replaced cooler (connected to C101) - non-detect results	-	-
Drinking	IKE824C108	Cooler	1.8	NO	4/10/2017	6.7	NO	4/10/2017	-	-	-	Replaced cooler (connected to C109) - non-detect results	-	-
Drinking	IKE824C109	Cooler	21	YES	4/10/2017	NA	NA	4/10/2017	1.2	5.3	7.5	Replaced cooler	non-detect	non-detect
Drinking	IKE824C112	Cooler	non-detect	NO	4/10/2017	0.91	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824C113	Cooler	1.2	NO	4/10/2017	1.3	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824C114	Cooler	0.52	NO	4/10/2017	1.1	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824C115	Cooler	0.96	NO	4/10/2017	1.6	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824C116	Cooler	1	NO	4/10/2017	1.2	NO	4/10/2017	-	-	-	Replaced cooler (high risk) due to past exceedance	non-detect	-
Drinking	IKE824C117	Cooler	3.6	NO	4/10/2017	2.0	NO	4/10/2017	-	-	-	Replaced cooler (high risk) due to past exceedance	non-detect	-
Drinking	IKE824C178	Cooler	2.3	NO	4/10/2017	1.2	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824C179	Cooler	2.3	NO	4/10/2017	1.2	NO	4/10/2017	-	-	-		-	-
Cooking/Brushing	IKE824F55	Faucet	0.56	NO	-	0.51	NO	-	-	-	-		-	-
Cooking/Brushing	IKE824F56	Faucet	0.51	NO	-	non-detect	NO	-	-	-	-		-	-
Cooking/Brushing	IKE824F57	Faucet	0.5	NO	-	non-detect	NO	-	-	-	-		-	-
Cooking/Brushing	IKE824F58	Faucet	0.56	NO	-	non-detect	NO	-	-	-	-		-	-
Cooking/Brushing	IKE824F59	Faucet	non-detect	NO	-	non-detect	NO	-	-	-	-		-	-
Cooking/Brushing	IKE824F61	Faucet	26	YES	4/10/2017	NA	NA	4/10/2017	NA	20	4.8	Faucet replaced on 8/1/2017.	2.6	1
Cooking/Brushing	IKE824F62	Faucet	27	YES	5/5/2017	NA	NA	5/5/2017	NA	17	3.3	Faucet replaced on 8/1/2017.	1.9	not-detect
Cooking/Brushing	IKE824F63	Faucet	16	NO	-	3.7	NO	-	-	-	-	Replaced faucet (high risk) due to past exceedance	1.7	-
Washing	IKE824F299	Faucet	0.94	NO	-	0.76	NO	-	-	-	-		-	-
Washing	IKE824F104	Faucet	0.56	NO	4/10/2017	non-detect	NO	4/10/2017	-	-	-		-	-
Washing	IKE824F105	Faucet	non-detect	NO	4/10/2017	2.4	NO	4/10/2017	-	-	-		-	-
Washing	IKE824F106	Faucet	1.1	NO	4/10/2017	0.94	NO	4/10/2017	-	-	-		-	-
Drinking	IKE824F025	Faucet	0.68	NO	-	0.62	NO	-	-	-	-		-	-
Drinking	IKE824F028	Faucet	non-detect	NO	-	non-detect	NO	-	-	-	-		-	-
Washing	IKE824F026	Faucet	1.1	NO	-	0.85	NO	-	-	-	-		-	-
Washing	IKE824F183	Faucet	0.92	NO	-	0.7	NO	-	-	-	-		-	-
Drinking	IKE824F016	Faucet	1.7	NO	-	0.67	NO	-	-	-	-		-	-
Drinking	IKE824F018	Faucet	5.1	NO	-	0.53	NO	-	-	-	-		-	-
Drinking	IKE824F033	Faucet	1.0	NO	-	0.74	NO	-	-	-	-		-	-
Drinking	IKE824F036	Faucet	3.2	NO	-	1.4	NO	-	-	-	-		-	-

SAMPLE LOCATION DESCRIPTION			INITIAL FULL BUILDING SAMPLING RESULTS			SECOND FULL BUILDING SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 20ppb						Water Fountain 15 min. Follow up Flush Sample Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush Collected 30 seconds after First Draw Sampling (ppb)	Description	Recommended Level = 20ppb	
			First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)					First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
Drinking	IKE824F039	Faucet	1.3	NO	-	0.71	NO	-	-	-	-	-	-	-
Drinking	IKE824F042	Faucet	4.0	NO	-	2.8	NO	-	-	-	-	-	-	-
Drinking	IKE824F232	Faucet	3.0	NO	-	1.3	NO	-	-	-	-	-	-	-
Drinking	IKE824F086	Faucet	0.86	NO	-	0.58	NO	-	-	-	-	-	-	-
Drinking	IKE824F092	Faucet	0.98	NO	-	1.5	NO	-	-	-	-	-	-	-
Drinking	IKE824F138	Faucet	0.91	NO	-	1.3	NO	-	-	-	-	-	-	-
Washing	IKE824F143	Faucet	4.0	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Entire pedestal fountain will be replaced.	-	-
Washing	IKE824F144	Faucet	9.9	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Entire pedestal fountain will be replaced.	-	-
Washing	IKE824F148	Faucet	1.9	NO	4/10/2017	5.5	NO	4/10/2017	-	-	-	-	-	-
Washing	IKE824F149	Faucet	3.9	NO	4/10/2017	9.5	NO	4/10/2017	-	-	-	-	-	-
Washing	IKE824F150	Faucet	5.3	NO	4/10/2017	23	YES	4/10/2017	NA	31	0.76	Entire pedestal fountain will be replaced.	-	-
Washing	IKE824F151	Faucet	8.4	NO	4/10/2017	15	NO	4/10/2017	-	-	-	-	-	-
Washing	IKE824F159	Faucet	8.5	NO	4/10/2017	1.8	NO	4/10/2017	-	-	-	-	-	-
Washing	IKE824F160	Faucet	3.2	NO	4/10/2017	1.3	NO	4/10/2017	-	-	-	-	-	-
Washing	IKE824F161	Faucet	3.7	NO	4/10/2017	6.2	NO	4/10/2017	-	-	-	-	-	-
Washing	IKE824F162	Faucet	1.9	NO	4/10/2017	14	NO	4/10/2017	-	-	-	-	-	-
Washing	IKE824F163	Faucet	9.5	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Entire pedestal fountain will be replaced.	-	-
Washing	IKE824F164	Faucet	4.3	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Entire pedestal fountain will be replaced.	-	-
Washing	IKE824F167	Faucet	2.4	NO	4/10/2017	5.3	NO	4/10/2017	-	-	-	-	-	-
Washing	IKE824F168	Faucet	0.54	NO	4/10/2017	3.4	NO	4/10/2017	-	-	-	-	-	-
SAMPLING DATE			5/10-12/2017			8/7-8/9/2017			NA	6/16/2017	6/16/2017		9/20/2017	
RESULTS DATE			6/20/2017			9/1/2017			NA	7/20/2017	7/20/2017		10/26/2017	
Washing	IKE824F187	Motion Sensor Faucet	2.3	NO	-	4.7	NO	-	-	-	-	-	-	-
Washing	IKE824F188	Motion Sensor Faucet	1.9	NO	-	7	NO	-	-	-	-	-	-	-
Washing	IKE824F019	Motion Sensor Faucet	2.3	NO	-	4.4	NO	-	-	-	-	-	-	-
Washing	IKE824F190	Motion Sensor Faucet	1.9	NO	-	1.6	NO	-	-	-	-	-	-	-
Washing	IKE824F191	Motion Sensor Faucet	1.2	NO	-	1.4	NO	-	-	-	-	-	-	-
Washing	IKE824F192	Motion Sensor Faucet	0.94	NO	-	1.6	NO	-	-	-	-	-	-	-
Washing	IKE824F193	Motion Sensor Faucet	5.6	NO	-	6.1	NO	-	-	-	-	-	-	-
Washing	IKE824F194	Motion Sensor Faucet	2.1	NO	-	2.1	NO	-	-	-	-	-	-	-
Washing	IKE824F195	Motion Sensor Faucet	8.6	NO	-	4.3	NO	-	-	-	-	-	-	-
Washing	IKE824F029	Motion Sensor Faucet	5.4	NO	-	6.4	NO	-	-	-	-	-	-	-
Washing	IKE824F043	Motion Sensor Faucet	1.3	NO	-	1.5	NO	-	-	-	-	-	-	-
Washing	IKE824F189	Motion Sensor Faucet	2.6	NO	-	2.6	NO	-	-	-	-	-	-	-
Washing	IKE824F296	Motion Sensor Faucet	37	YES	-	NA	NA	8/22/2017	NA	36	16	Replaced faucet	9.6	4.0
Washing	IKE824F197	Motion Sensor Faucet	2.4	NO	-	3.1	NO	-	-	-	-	-	-	-
Washing	IKE824F198	Motion Sensor Faucet	2.9	NO	-	4.9	NO	-	-	-	-	-	-	-
Washing	IKE824F199	Motion Sensor Faucet	1.2	NO	-	2	NO	-	-	-	-	-	-	-
Washing	IKE824F200	Motion Sensor Faucet	1	NO	-	1.5	NO	-	-	-	-	-	-	-
Washing	IKE824F201	Motion Sensor Faucet	3.1	NO	-	0.79	NO	-	-	-	-	-	-	-
Washing	IKE824F202	Motion Sensor Faucet	2	NO	-	3.9	NO	-	-	-	-	-	-	-
Washing	IKE824F203	Motion Sensor Faucet	1.9	NO	-	5.6	NO	-	-	-	-	-	-	-
Washing	IKE824F204	Motion Sensor Faucet	1.8	NO	-	2	NO	-	-	-	-	-	-	-
Washing	IKE824F012	Motion Sensor Faucet	1.6	NO	-	5.1	NO	-	-	-	-	-	-	-
Washing	IKE824F013	Motion Sensor Faucet	0.94	NO	-	1.3	NO	-	-	-	-	-	-	-
Washing	IKE824F207	Motion Sensor Faucet	2.1	NO	-	2.3	NO	-	-	-	-	-	-	-
Washing	IKE824F208	Motion Sensor Faucet	2	NO	-	3.1	NO	-	-	-	-	-	-	-
Washing	IKE824F209	Motion Sensor Faucet	1.9	NO	-	2	NO	-	-	-	-	-	-	-
Washing	IKE824F210	Motion Sensor Faucet	2	NO	-	3.3	NO	-	-	-	-	-	-	-
Washing	IKE824F034	Motion Sensor Faucet	3.9	NO	-	4.6	NO	-	-	-	-	-	-	-
Washing	IKE824F184	Motion Sensor Faucet	1.5	NO	-	1.9	NO	-	-	-	-	-	-	-
Washing	IKE824F211	Motion Sensor Faucet	3.4	NO	-	10	NO	-	-	-	-	-	-	-
Washing	IKE824F212	Motion Sensor Faucet	3.4	NO	-	12	NO	-	-	-	-	-	-	-
Washing	IKE824F213	Motion Sensor Faucet	2.9	NO	-	8.8	NO	-	-	-	-	-	-	-
Washing	IKE824F037	Motion Sensor Faucet	0.79	NO	-	4.4	NO	-	-	-	-	-	-	-
Washing	IKE824F185	Motion Sensor Faucet	1.7	NO	-	3.2	NO	-	-	-	-	-	-	-
Washing	IKE824F214	Motion Sensor Faucet	3.2	NO	-	5.6	NO	-	-	-	-	-	-	-
Washing	IKE824F215	Motion Sensor Faucet	2.3	NO	-	4	NO	-	-	-	-	-	-	-
Washing	IKE824F216	Motion Sensor Faucet	2.8	NO	-	4.6	NO	-	-	-	-	-	-	-
Washing	IKE824F040	Motion Sensor Faucet	2.8	NO	-	4.6	NO	-	-	-	-	-	-	-
Washing	IKE824F186	Motion Sensor Faucet	1.6	NO	-	2.8	NO	-	-	-	-	-	-	-
Washing	IKE824F217	Motion Sensor Faucet	1.6	NO	-	2.2	NO	-	-	-	-	-	-	-

SAMPLE LOCATION DESCRIPTION			INITIAL FULL BUILDING SAMPLING RESULTS			SECOND FULL BUILDING SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 20ppb						Water Fountain 15 min. Follow up Flush Sample Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush Collected 30 seconds after First Draw Sampling (ppb)	Description	Recommended Level = 20ppb	
			First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)					First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
Washing	IKE824F218	Motion Sensor Faucet	1.1	NO	-	1.5	NO	-	-	-	-	-	-	-
Washing	IKE824F297	Motion Sensor Faucet	1.1	NO	-	1.3	NO	-	-	-	-	-	-	-
Washing	IKE824F219	Motion Sensor Faucet	1.1	NO	-	2	NO	-	-	-	-	-	-	-
Washing	IKE824F220	Motion Sensor Faucet	3.3	NO	-	22	YES	8/25/2017	NA	4.1	1.4	Replaced faucet	2.8	non-detect
Washing	IKE824F221	Motion Sensor Faucet	1.6	NO	-	2.1	NO	-	-	-	-	-	-	-
Washing	IKE824F222	Motion Sensor Faucet	5.9	NO	-	5.4	NO	-	-	-	-	-	-	-
Washing	IKE824F223	Motion Sensor Faucet	7	NO	-	0.98	NO	-	-	-	-	-	-	-
Washing	IKE824F224	Motion Sensor Faucet	6	NO	-	10	NO	-	-	-	-	-	-	-
Washing	IKE824F298	Motion Sensor Faucet	3.5	NO	-	4.1	NO	-	-	-	-	-	-	-
Washing	IKE824F225	Motion Sensor Faucet	3.7	NO	-	5.4	NO	-	-	-	-	-	-	-
Washing	IKE824F226	Motion Sensor Faucet	2.8	NO	-	3.7	NO	-	-	-	-	-	-	-
Washing	IKE824F227	Motion Sensor Faucet	3.4	NO	-	4.3	NO	-	-	-	-	-	-	-
Washing	IKE824F228	Motion Sensor Faucet	5.2	NO	-	4.8	NO	-	-	-	-	-	-	-
Washing	IKE824F229	Motion Sensor Faucet	4.1	NO	-	5.5	NO	-	-	-	-	-	-	-
Washing	IKE824F230	Motion Sensor Faucet	3.8	NO	-	4.5	NO	-	-	-	-	-	-	-
Washing	IKE824F300	Motion Sensor Faucet	6.8	NO	-	8.1	NO	-	-	-	-	-	-	-
Washing	IKE824F231	Motion Sensor Faucet	4.6	NO	-	6.7	NO	-	-	-	-	-	-	-
Washing	IKE824F233	Motion Sensor Faucet	0.55	NO	-	non-detect	NO	-	-	-	-	-	-	-
Washing	IKE824F065	Motion Sensor Faucet	0.92	NO	-	1	NO	-	-	-	-	-	-	-
Washing	IKE824F070	Motion Sensor Faucet	2.2	NO	-	2	NO	-	-	-	-	-	-	-
Washing	IKE824F071	Motion Sensor Faucet	1	NO	-	2.2	NO	-	-	-	-	-	-	-
Washing	IKE824F234	Motion Sensor Faucet	1.7	NO	-	1.7	NO	-	-	-	-	-	-	-
Washing	IKE824F235	Motion Sensor Faucet	9.8	NO	-	6.7	NO	-	-	-	-	-	-	-
Washing	IKE824F236	Motion Sensor Faucet	3.3	NO	-	9.2	NO	-	-	-	-	-	-	-
Washing	IKE824F237	Motion Sensor Faucet	8	NO	-	0.94	NO	-	-	-	-	-	-	-
Washing	IKE824F238	Motion Sensor Faucet	3.9	NO	-	1.3	NO	-	-	-	-	-	-	-
Washing	IKE824F239	Motion Sensor Faucet	4.3	NO	-	3.9	NO	-	-	-	-	-	-	-
Washing	IKE824F240	Motion Sensor Faucet	1.3	NO	-	1.1	NO	-	-	-	-	-	-	-
Washing	IKE824F241	Motion Sensor Faucet	2.4	NO	-	2.4	NO	-	-	-	-	-	-	-
Washing	IKE824F242	Motion Sensor Faucet	1.4	NO	-	1.9	NO	-	-	-	-	-	-	-
Washing	IKE824F243	Motion Sensor Faucet	1.4	NO	-	3	NO	-	-	-	-	-	-	-
Washing	IKE824F244	Motion Sensor Faucet	2.4	NO	-	2.2	NO	-	-	-	-	-	-	-
Washing	IKE824F245	Motion Sensor Faucet	1.9	NO	-	1.6	NO	-	-	-	-	-	-	-
Washing	IKE824F246	Motion Sensor Faucet	1.4	NO	-	1.4	NO	-	-	-	-	-	-	-
Washing	IKE824F247	Motion Sensor Faucet	0.88	NO	-	1.1	NO	-	-	-	-	-	-	-
Washing	IKE824F248	Motion Sensor Faucet	1.2	NO	-	1.5	NO	-	-	-	-	-	-	-
Washing	IKE824F249	Motion Sensor Faucet	0.77	NO	-	1.1	NO	-	-	-	-	-	-	-
Washing	IKE824F250	Motion Sensor Faucet	2.1	NO	-	0.89	NO	-	-	-	-	-	-	-
Washing	IKE824F251	Motion Sensor Faucet	2.9	NO	-	3.4	NO	-	-	-	-	-	-	-
Washing	IKE824F252	Motion Sensor Faucet	2.4	NO	-	2.2	NO	-	-	-	-	-	-	-
Washing	IKE824F253	Motion Sensor Faucet	3	NO	-	2.3	NO	-	-	-	-	-	-	-
Washing	IKE824F075	Motion Sensor Faucet	0.66	NO	-	0.91	NO	-	-	-	-	-	-	-
Washing	IKE824F076	Motion Sensor Faucet	2.2	NO	-	4.5	NO	-	-	-	-	-	-	-
Washing	IKE824F254	Motion Sensor Faucet	2.7	NO	-	2.7	NO	-	-	-	-	-	-	-
Washing	IKE824F255	Motion Sensor Faucet	2.4	NO	-	2.4	NO	-	-	-	-	-	-	-
Washing	IKE824F257	Motion Sensor Faucet	1.5	NO	-	2.3	NO	-	-	-	-	-	-	-
Washing	IKE824F258	Motion Sensor Faucet	2.7	NO	-	5.3	NO	-	-	-	-	-	-	-
Washing	IKE824F259	Motion Sensor Faucet	1.5	NO	-	1.9	NO	-	-	-	-	-	-	-
Washing	IKE824F260	Motion Sensor Faucet	2	NO	-	2.1	NO	-	-	-	-	-	-	-
Washing	IKE824F261	Motion Sensor Faucet	1.4	NO	-	2.3	NO	-	-	-	-	-	-	-
Washing	IKE824F262	Motion Sensor Faucet	5.8	NO	-	6.9	NO	-	-	-	-	-	-	-
Washing	IKE824F256	Motion Sensor Faucet	2.1	NO	-	2.6	NO	-	-	-	-	-	-	-
Washing	IKE824F263	Motion Sensor Faucet	1.3	NO	-	2.3	NO	-	-	-	-	-	-	-
Washing	IKE824F264	Motion Sensor Faucet	0.92	NO	-	1.2	NO	-	-	-	-	-	-	-
Washing	IKE824F111	Motion Sensor Faucet	1.1	NO	-	2.6	NO	-	-	-	-	-	-	-
Washing	IKE824F103	Motion Sensor Faucet	non-detect	NO	-	38	YES	8/25/2017	NA	9.1	1.6	Awaiting faucet replacement.	-	-
Washing	IKE824F265	Motion Sensor Faucet	non-detect	NO	-	0.53	NO	-	-	-	-	-	-	-
Washing	IKE824F266	Motion Sensor Faucet	non-detect	NO	-	3.5	NO	-	-	-	-	-	-	-
Washing	IKE824F267	Motion Sensor Faucet	non-detect	NO	-	1.4	NO	-	-	-	-	-	-	-
Washing	IKE824F268	Motion Sensor Faucet	non-detect	NO	-	4.1	NO	-	-	-	-	-	-	-
Washing	IKE824F269	Motion Sensor Faucet	non-detect	NO	-	2	NO	-	-	-	-	-	-	-
Washing	IKE824F270	Motion Sensor Faucet	8.7	NO	-	5.5	NO	-	-	-	-	-	-	-

SAMPLE LOCATION DESCRIPTION			INITIAL FULL BUILDING SAMPLING RESULTS			SECOND FULL BUILDING SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS		
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 20ppb									Description	Recommended Level = 20ppb		
			First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush Collected 30 seconds after First Draw Sampling (ppb)		First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	
Washing	IKE824F271	Motion Sensor Faucet	non-detect	NO	-	1.2	NO	-	-	-	-	-	-	-	-
Washing	IKE824F273	Motion Sensor Faucet	non-detect	NO	-	1.7	NO	-	-	-	-	-	-	-	-
Washing	IKE824F274	Motion Sensor Faucet	2.6	NO	-	10	NO	-	-	-	-	-	-	-	-
Washing	IKE824F272	Motion Sensor Faucet	8	NO	-	8.6	NO	-	-	-	-	-	-	-	-
Washing	IKE824F275	Motion Sensor Faucet	non-detect	NO	-	1	NO	-	-	-	-	-	-	-	-
Washing	IKE824F276	Motion Sensor Faucet	non-detect	NO	-	1.9	NO	-	-	-	-	-	-	-	-
Washing	IKE824F277	Motion Sensor Faucet	non-detect	NO	-	1.8	NO	-	-	-	-	-	-	-	-
Washing	IKE824F278	Motion Sensor Faucet	non-detect	NO	-	0.63	NO	-	-	-	-	-	-	-	-
Washing	IKE824F279	Motion Sensor Faucet	0.92	NO	-	2.2	NO	-	-	-	-	-	-	-	-
Washing	IKE824F280	Motion Sensor Faucet	1.1	NO	-	2.2	NO	-	-	-	-	-	-	-	-
Washing	IKE824F281	Motion Sensor Faucet	2	NO	-	1.3	NO	-	-	-	-	-	-	-	-
Washing	IKE824F282	Motion Sensor Faucet	1.3	NO	-	1	NO	-	-	-	-	-	-	-	-
Washing	IKE824F124	Motion Sensor Faucet	0.82	NO	-	0.9	NO	-	-	-	-	-	-	-	-
Washing	IKE824F125	Motion Sensor Faucet	1.6	NO	-	1.8	NO	-	-	-	-	-	-	-	-
Washing	IKE824F283	Motion Sensor Faucet	non-detect	NO	-	0.85	NO	-	-	-	-	-	-	-	-
Washing	IKE824F284	Motion Sensor Faucet	2	NO	-	2.5	NO	-	-	-	-	-	-	-	-
Washing	IKE824F286	Motion Sensor Faucet	non-detect	NO	-	1.4	NO	-	-	-	-	-	-	-	-
Washing	IKE824F287	Motion Sensor Faucet	1.6	NO	-	1.7	NO	-	-	-	-	-	-	-	-
Washing	IKE824F288	Motion Sensor Faucet	1.8	NO	-	2.1	NO	-	-	-	-	-	-	-	-
Washing	IKE824F285	Motion Sensor Faucet	4.5	NO	-	7.9	NO	-	-	-	-	-	-	-	-
Washing	IKE824F289	Motion Sensor Faucet	1.3	NO	-	1.3	NO	-	-	-	-	-	-	-	-
Washing	IKE824F291	Motion Sensor Faucet	0.94	NO	-	1	NO	-	-	-	-	-	-	-	-
Washing	IKE824F292	Motion Sensor Faucet	1.3	NO	-	1.9	NO	-	-	-	-	-	-	-	-
Washing	IKE824F290	Motion Sensor Faucet	0.71	NO	-	1	NO	-	-	-	-	-	-	-	-
Washing	IKE824F293	Motion Sensor Faucet	1.7	NO	-	1	NO	-	-	-	-	-	-	-	-
Washing	IKE824F294	Motion Sensor Faucet	12	NO	-	17	NO	-	-	-	-	-	-	-	-
Washing	IKE824F295	Motion Sensor Faucet	11	NO	-	20	YES	8/25/2017	NA	17	0.54	Awaiting faucet replacement.	-	-	-

Notes:

¹ Faucets that were unsecured were permitted for handwashing and dishwashing use per BUMED concurrence. Kitchen faucet F62 was physically secured upon notification of exceedance on 5/5/2017, however the faucet was not used by kitchen staff as of 4/10/2017

² Second full building sampling excluded fixtures that were scheduled for replacement.

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS	SECOND SAMPLING RESULTS	RE-SAMPLING RESULTS			POST REMEDIATION RESULTS
	Recommended Level = 20ppb					
	First Draw (ppb)	First Draw (ppb)	Water Fountain Follow up Flush	First Draw (ppb)	Follow up Flush - Collected 30	First Draw (ppb)
Total Drinking	87	65	2	9	9	27
Total Drinking > 20 ppb	9	0	0	3	0	0
Total Cooking/Brushing	8	6	0	2	2	3
Total Cooking/Brushing > 20 ppb	2	0	0	1	0	0
Total Washing	149	144	0	5	5	2
Total Washing > 20 ppb	1	4	0	2	0	0
Total Samples	244	215	2	16	16	32
Total Samples > 20 ppb	12	4	0	6	0	0