

**Priority Areas Lead Testing and Corrective Action
Ikego Elementary School - bldg 824 (FULL RESULTS AS OF 29 Aug 18)**

SAMPLE LOCATION DESCRIPTION			INITIAL FULL BUILDING SAMPLING RESULTS			SECOND FULL BUILDING SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS		
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 20ppb									Description	Recommended Level = 20ppb		
			First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush Collected 30 seconds after First Draw Sampling (ppb)		First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	
SAMPLING DATE			4/15, 4/19-21/2017			7/25-28/2017			6/15/2017			6/16/2017		8/4/17 & 9/19-21/17, 4/11/18	
RESULTS DATE			5/17/2017			8/29/2017			7/20/2017			7/20/2017		8/28/17, 10/26/17, 5/31/18	
Drinking	IKE8248015	Bubbler	0.7	NO	4/10/2017	non-detect	NO	4/10/2017	-	-	-	-	-	-	
Drinking	IKE8248021	Bubbler	7.9	NO	4/10/2017	non-detect	NA	4/10/2017	-	-	-	-	-	-	
Drinking	IKE8248022	Bubbler	27	YES	4/10/2017	NA	NA	4/10/2017	NA	11	2.1	Replaced bubbler	6.5	2.1	
Drinking	IKE8248023	Bubbler	6.0	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	1.4	-	
Drinking	IKE8248027	Bubbler	4.6	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	5.8	-	
Drinking	IKE8248017	Bubbler	5.3	NO	4/10/2017	non-detect	NO	4/10/2017	-	-	-	-	-	-	
Drinking	IKE8248044	Bubbler	9.5	NO	4/10/2017	0.53	NO	4/10/2017	-	-	-	-	-	-	
Drinking	IKE8248045	Bubbler	6.0	NO	4/10/2017	1.1	NO	4/10/2017	-	-	-	-	-	-	
Drinking	IKE8248046	Bubbler	5.7	NO	4/10/2017	1.6	NO	4/10/2017	-	-	-	-	-	-	
Drinking	IKE8248047	Bubbler	9.9	NO	4/10/2017	non-detect	NO	4/10/2017	-	-	-	-	-	-	
Drinking	IKE8248048	Bubbler	3.8	NO	4/10/2017	non-detect	NO	4/10/2017	-	-	-	-	-	-	
Drinking	IKE8248014	Bubbler	2.8	NO	4/10/2017	0.87	NO	4/10/2017	-	-	-	-	-	-	
Drinking	IKE8248049	Bubbler	3.8	NO	4/10/2017	non-detect	NO	4/10/2017	-	-	-	-	-	-	
Drinking	IKE8248032	Bubbler	6.6	NO	4/10/2017	non-detect	NO	4/10/2017	-	-	-	-	-	-	
Drinking	IKE8248035	Bubbler	11	NO	4/10/2017	0.5	NO	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	0.68	-	
Drinking	IKE8248038	Bubbler	7.6	NO	4/10/2017	1.1	NO	4/10/2017	-	-	-	-	-	-	
Drinking	IKE8248050	Bubbler	0.75	NO	4/10/2017	non-detect	NO	4/10/2017	-	-	-	-	-	-	
Drinking	IKE8248051	Bubbler	2.2	NO	4/10/2017	0.66	NO	4/10/2017	-	-	-	-	-	-	
Drinking	IKE8248041	Bubbler	3.5	NO	4/10/2017	4.5	NO	4/10/2017	-	-	-	-	-	-	
Drinking	IKE8248053	Bubbler	8.2	NO	4/10/2017	2.9	NO	4/10/2017	-	-	-	-	-	-	
Drinking	IKE8248054	Bubbler	2.1	NO	4/10/2017	non-detect	NO	4/10/2017	-	-	-	-	-	-	
Drinking	IKE8248087	Bubbler	34	YES	4/10/2017	NA	NA	4/10/2017	NA	29	8.9	Replaced bubbler	7.2	0.88	
Drinking	IKE8248088	Bubbler	79	YES	4/10/2017	NA	NA	4/10/2017	NA	40	11	Replaced bubbler	9.4	1.7	
Drinking	IKE8248089	Bubbler	88	YES	4/10/2017	NA	NA	4/10/2017	NA	28	12	Replaced bubbler	8.2	3.3	
Drinking	IKE8248090	Bubbler	30	YES	4/10/2017	NA	NA	4/10/2017	NA	10	3.8	Replaced bubbler	6.8	3	
Drinking	IKE8248091	Bubbler	24	YES	4/10/2017	NA	NA	4/10/2017	NA	7.1	14	Replaced bubbler	4.3	1.3	
Drinking	IKE8248094	Bubbler	13	NO	4/10/2017	1.7	NO	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	4.6	-	
Drinking	IKE8248081	Bubbler	19	NO	4/10/2017	2.0	NO	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	3.1	1.4	
Drinking	IKE8248077	Bubbler	8.5	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	2.7	-	
Drinking	IKE8248078	Bubbler	9.3	NO	4/10/2017	1.2	NO	4/10/2017	-	-	-	-	-	-	
Drinking	IKE8248079	Bubbler	6.9	NO	4/10/2017	1.7	NO	4/10/2017	-	-	-	-	-	-	
Drinking	IKE8248080	Bubbler	1.9	NO	4/10/2017	2.0	NO	4/10/2017	-	-	-	-	-	-	
Drinking	IKE8248082	Bubbler	2.8	NO	4/10/2017	0.83	NO	4/10/2017	-	-	-	-	-	-	
Drinking	IKE8248083	Bubbler	4.6	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	3.5	-	
Drinking	IKE8248093	Bubbler	5.7	NO	4/10/2017	1.2	NO	4/10/2017	-	-	-	-	-	-	
Drinking	IKE8248084	Bubbler	5.1	NO	4/10/2017	5.3	NO	4/10/2017	-	-	-	-	-	-	
Drinking	IKE8248085	Bubbler	2.1	NO	4/10/2017	0.77	NO	4/10/2017	-	-	-	-	-	-	
Drinking	IKE8248139	Bubbler	2.1	NO	4/10/2017	1.7	NO	4/10/2017	-	-	-	-	-	-	
Drinking	IKE8248140	Bubbler	5.7	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	7.2	-	
Drinking	IKE8248141	Bubbler	17	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	7.2	-	
Drinking	IKE8248142	Bubbler	3.4	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	4	-	
Drinking	IKE8248135	Bubbler	5.5	NO	4/10/2017	3.9	NO	4/10/2017	-	-	-	-	-	-	
Drinking	IKE8248126	Bubbler	6.7	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	1.8	-	

SAMPLE LOCATION DESCRIPTION			INITIAL FULL BUILDING SAMPLING RESULTS			SECOND FULL BUILDING SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 20ppb									Description	Recommended Level = 20ppb	
			First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush Collected 30 seconds after First Draw Sampling (ppb)		First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
Drinking	IKE824B132	Bubbler	3.5	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	2.1	-
Drinking	IKE824B127	Bubbler	9.0	NO	4/10/2017	3.8	NO	4/10/2017	-	-	-	-	-	-
Drinking	IKE824B133	Bubbler	4.7	NO	4/10/2017	5.9	NO	4/10/2017	-	-	-	-	-	-
Drinking	IKE824B128	Bubbler	9.3	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	2	-
Drinking	IKE824B134	Bubbler	7.0	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	7.1	-
Drinking	IKE824B129	Bubbler	6.4	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	2.5	-
Drinking	IKE824B130	Bubbler	2.2	NO	4/10/2017	1.6	NO	4/10/2017	-	-	-	-	-	-
Drinking	IKE824B131	Bubbler	6.8	NO	4/10/2017	2.3	NO	4/10/2017	-	-	-	-	-	-
Drinking	IKE824B136	Bubbler	6.3	NO	4/10/2017	NA	NA	4/10/2017	-	-	-	Replaced bubbler (high risk) due to past exceedance	2.3	-
Drinking	IKE824B137	Bubbler	25	YES	4/10/2017	NA	NA	4/10/2017	NA	14	2.2	Replaced bubbler	7.5	1.4
Drinking	IKE824C1	Cooler	0.74	NO	4/10/2017	2.4	NO	4/10/2017	-	-	-	-	-	-
Drinking	IKE824C2	Cooler	3.4	NO	4/10/2017	1.3	NO	4/10/2017	-	-	-	-	-	-
Drinking	IKE824C3	Cooler	0.63	NO	4/10/2017	0.9	NO	4/10/2017	-	-	-	-	-	-
Drinking	IKE824C4	Cooler	5.7	NO	4/10/2017	0.86	NO	4/10/2017	-	-	-	-	-	-
Drinking	IKE824C5	Cooler	0.67	NO	4/10/2017	1.7	NO	4/10/2017	-	-	-	-	-	-
Drinking	IKE824C6	Cooler	1.2	NO	4/10/2017	2.5	NO	4/10/2017	-	-	-	-	-	-
Drinking	IKE824C66	Cooler	1.4	NO	4/10/2017	2.3	NO	4/10/2017	-	-	-	-	-	-
Drinking	IKE824C67	Cooler	0.61	NO	4/10/2017	2.0	NO	4/10/2017	-	-	-	-	-	-
Drinking	IKE824C68	Cooler	non-detect	NO	4/10/2017	0.73	NO	4/10/2017	-	-	-	-	-	-
Drinking	IKE824C69	Cooler	non-detect	NO	4/10/2017	1.3	NO	4/10/2017	-	-	-	-	-	-
Drinking	IKE824C101	Cooler	32	YES	4/10/2017	NA	NA	4/10/2017	0.76	5.4	5.8	Replaced cooler	non-detect	non-detect
Drinking	IKE824C102	Cooler	10	NO	4/10/2017	7.0	NO	4/10/2017	-	-	-	Replaced cooler (connected to C101) - non-detect results	-	-
Drinking	IKE824C108	Cooler	1.8	NO	4/10/2017	6.7	NO	4/10/2017	-	-	-	Replaced cooler (connected to C109) - non-detect results	-	-
Drinking	IKE824C109	Cooler	21	YES	4/10/2017	NA	NA	4/10/2017	1.2	5.3	7.5	Replaced cooler	non-detect	non-detect
Drinking	IKE824C112	Cooler	non-detect	NO	4/10/2017	0.91	NO	4/10/2017	-	-	-	-	-	-
Drinking	IKE824C113	Cooler	1.2	NO	4/10/2017	1.3	NO	4/10/2017	-	-	-	-	-	-
Drinking	IKE824C114	Cooler	0.52	NO	4/10/2017	1.1	NO	4/10/2017	-	-	-	-	-	-
Drinking	IKE824C115	Cooler	0.96	NO	4/10/2017	1.6	NO	4/10/2017	-	-	-	-	-	-
Drinking	IKE824C116	Cooler	1	NO	4/10/2017	1.2	NO	4/10/2017	-	-	-	Replaced cooler (high risk) due to past exceedance	non-detect	-
Drinking	IKE824C117	Cooler	3.6	NO	4/10/2017	2.0	NO	4/10/2017	-	-	-	Replaced cooler (high risk) due to past exceedance	non-detect	-
Drinking	IKE824C178	Cooler	2.3	NO	4/10/2017	1.2	NO	4/10/2017	-	-	-	-	-	-
Drinking	IKE824C179	Cooler	2.3	NO	4/10/2017	1.2	NO	4/10/2017	-	-	-	-	-	-
Cooking/Brushing	IKE824F55	Faucet	0.56	NO	-	0.51	NO	-	-	-	-	-	-	-
Cooking/Brushing	IKE824F56	Faucet	0.51	NO	-	non-detect	NO	-	-	-	-	-	-	-
Cooking/Brushing	IKE824F57	Faucet	0.5	NO	-	non-detect	NO	-	-	-	-	-	-	-
Cooking/Brushing	IKE824F58	Faucet	0.56	NO	-	non-detect	NO	-	-	-	-	-	-	-
Cooking/Brushing	IKE824F59	Faucet	non-detect	NO	-	non-detect	NO	-	-	-	-	-	-	-
Cooking/Brushing	IKE824F61	Faucet	26	YES	4/10/2017	NA	NA	4/10/2017	NA	20	4.8	Faucet replaced on 8/1/2017.	2.6	1
Cooking/Brushing	IKE824F62	Faucet	27	YES	5/5/2017	NA	NA	5/5/2017	NA	17	3.3	Faucet replaced on 8/1/2017.	1.9	non-detect
Cooking/Brushing	IKE824F63	Faucet	16	NO	-	3.7	NO	-	-	-	-	Replaced faucet (high risk) due to past exceedance	1.7	-
Washing	IKE824F299	Faucet	0.94	NO	-	0.76	NO	-	-	-	-	-	-	-
Washing	IKE824F104	Faucet	0.56	NO	4/10/2017	non-detect	NO	4/10/2017	-	-	-	-	-	-
Washing	IKE824F105	Faucet	non-detect	NO	4/10/2017	2.4	NO	4/10/2017	-	-	-	-	-	-
Washing	IKE824F106	Faucet	1.1	NO	4/10/2017	0.94	NO	4/10/2017	-	-	-	-	-	-
Drinking	IKE824F025	Faucet	0.68	NO	-	0.62	NO	-	-	-	-	-	-	-
Drinking	IKE824F028	Faucet	non-detect	NO	-	non-detect	NO	-	-	-	-	-	-	-
Washing	IKE824F026	Faucet	1.1	NO	-	0.85	NO	-	-	-	-	-	-	-
Washing	IKE824F183	Faucet	0.92	NO	-	0.7	NO	-	-	-	-	-	-	-
Drinking	IKE824F016	Faucet	1.7	NO	-	0.67	NO	-	-	-	-	-	-	-
Drinking	IKE824F018	Faucet	5.1	NO	-	0.53	NO	-	-	-	-	-	-	-
Drinking	IKE824F033	Faucet	1.0	NO	-	0.74	NO	-	-	-	-	-	-	-
Drinking	IKE824F036	Faucet	3.2	NO	-	1.4	NO	-	-	-	-	-	-	-

SAMPLE LOCATION DESCRIPTION			INITIAL FULL BUILDING SAMPLING RESULTS			SECOND FULL BUILDING SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS		
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 20ppb									Description	Recommended Level = 20ppb		
			First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush Collected 30 seconds after First Draw Sampling (ppb)		First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	
Washing	IKE824F214	Motion Sensor Faucet	3.2	NO	-	5.6	NO	-	-	-	-	-	-	-	-
Washing	IKE824F215	Motion Sensor Faucet	2.3	NO	-	4	NO	-	-	-	-	-	-	-	-
Washing	IKE824F216	Motion Sensor Faucet	2.8	NO	-	4.6	NO	-	-	-	-	-	-	-	-
Washing	IKE824F040	Motion Sensor Faucet	2.8	NO	-	4.6	NO	-	-	-	-	-	-	-	-
Washing	IKE824F186	Motion Sensor Faucet	1.6	NO	-	2.8	NO	-	-	-	-	-	-	-	-
Washing	IKE824F217	Motion Sensor Faucet	1.6	NO	-	2.2	NO	-	-	-	-	-	-	-	-
Washing	IKE824F218	Motion Sensor Faucet	1.1	NO	-	1.5	NO	-	-	-	-	-	-	-	-
Washing	IKE824F297	Motion Sensor Faucet	1.1	NO	-	1.3	NO	-	-	-	-	-	-	-	-
Washing	IKE824F219	Motion Sensor Faucet	1.1	NO	-	2	NO	-	-	-	-	-	-	-	-
Washing	IKE824F220	Motion Sensor Faucet	3.3	NO	-	22	YES	8/25/2017	NA	4.1	1.4	Replaced faucet	2.8	non-detect	-
Washing	IKE824F221	Motion Sensor Faucet	1.6	NO	-	2.1	NO	-	-	-	-	-	-	-	-
Washing	IKE824F222	Motion Sensor Faucet	5.9	NO	-	5.4	NO	-	-	-	-	-	-	-	-
Washing	IKE824F223	Motion Sensor Faucet	7	NO	-	0.98	NO	-	-	-	-	-	-	-	-
Washing	IKE824F224	Motion Sensor Faucet	6	NO	-	10	NO	-	-	-	-	-	-	-	-
Washing	IKE824F298	Motion Sensor Faucet	3.5	NO	-	4.1	NO	-	-	-	-	-	-	-	-
Washing	IKE824F225	Motion Sensor Faucet	3.7	NO	-	5.4	NO	-	-	-	-	-	-	-	-
Washing	IKE824F226	Motion Sensor Faucet	2.8	NO	-	3.7	NO	-	-	-	-	-	-	-	-
Washing	IKE824F227	Motion Sensor Faucet	3.4	NO	-	4.3	NO	-	-	-	-	-	-	-	-
Washing	IKE824F228	Motion Sensor Faucet	5.2	NO	-	4.8	NO	-	-	-	-	-	-	-	-
Washing	IKE824F229	Motion Sensor Faucet	4.1	NO	-	5.5	NO	-	-	-	-	-	-	-	-
Washing	IKE824F230	Motion Sensor Faucet	3.8	NO	-	4.5	NO	-	-	-	-	-	-	-	-
Washing	IKE824F300	Motion Sensor Faucet	6.8	NO	-	8.1	NO	-	-	-	-	-	-	-	-
Washing	IKE824F231	Motion Sensor Faucet	4.6	NO	-	6.7	NO	-	-	-	-	-	-	-	-
Washing	IKE824F233	Motion Sensor Faucet	0.55	NO	-	non-detect	NO	-	-	-	-	-	-	-	-
Washing	IKE824F065	Motion Sensor Faucet	0.92	NO	-	1	NO	-	-	-	-	-	-	-	-
Washing	IKE824F070	Motion Sensor Faucet	2.2	NO	-	2	NO	-	-	-	-	-	-	-	-
Washing	IKE824F071	Motion Sensor Faucet	1	NO	-	2.2	NO	-	-	-	-	-	-	-	-
Washing	IKE824F234	Motion Sensor Faucet	1.7	NO	-	1.7	NO	-	-	-	-	-	-	-	-
Washing	IKE824F235	Motion Sensor Faucet	9.8	NO	-	6.7	NO	-	-	-	-	-	-	-	-
Washing	IKE824F236	Motion Sensor Faucet	3.3	NO	-	9.2	NO	-	-	-	-	-	-	-	-
Washing	IKE824F237	Motion Sensor Faucet	8	NO	-	0.94	NO	-	-	-	-	-	-	-	-
Washing	IKE824F238	Motion Sensor Faucet	3.9	NO	-	1.3	NO	-	-	-	-	-	-	-	-
Washing	IKE824F239	Motion Sensor Faucet	4.3	NO	-	3.9	NO	-	-	-	-	-	-	-	-
Washing	IKE824F240	Motion Sensor Faucet	1.3	NO	-	1.1	NO	-	-	-	-	-	-	-	-
Washing	IKE824F241	Motion Sensor Faucet	2.4	NO	-	2.4	NO	-	-	-	-	-	-	-	-
Washing	IKE824F242	Motion Sensor Faucet	1.4	NO	-	1.9	NO	-	-	-	-	-	-	-	-
Washing	IKE824F243	Motion Sensor Faucet	1.4	NO	-	3	NO	-	-	-	-	-	-	-	-
Washing	IKE824F244	Motion Sensor Faucet	2.4	NO	-	2.2	NO	-	-	-	-	-	-	-	-
Washing	IKE824F245	Motion Sensor Faucet	1.9	NO	-	1.6	NO	-	-	-	-	-	-	-	-
Washing	IKE824F246	Motion Sensor Faucet	1.4	NO	-	1.4	NO	-	-	-	-	-	-	-	-
Washing	IKE824F247	Motion Sensor Faucet	0.88	NO	-	1.1	NO	-	-	-	-	-	-	-	-
Washing	IKE824F248	Motion Sensor Faucet	1.2	NO	-	1.5	NO	-	-	-	-	-	-	-	-
Washing	IKE824F249	Motion Sensor Faucet	0.77	NO	-	1.1	NO	-	-	-	-	-	-	-	-
Washing	IKE824F250	Motion Sensor Faucet	2.1	NO	-	0.89	NO	-	-	-	-	-	-	-	-
Washing	IKE824F251	Motion Sensor Faucet	2.9	NO	-	3.4	NO	-	-	-	-	-	-	-	-
Washing	IKE824F252	Motion Sensor Faucet	2.4	NO	-	2.2	NO	-	-	-	-	-	-	-	-
Washing	IKE824F253	Motion Sensor Faucet	3	NO	-	2.3	NO	-	-	-	-	-	-	-	-
Washing	IKE824F075	Motion Sensor Faucet	0.66	NO	-	0.91	NO	-	-	-	-	-	-	-	-
Washing	IKE824F076	Motion Sensor Faucet	2.2	NO	-	4.5	NO	-	-	-	-	-	-	-	-
Washing	IKE824F254	Motion Sensor Faucet	2.7	NO	-	2.7	NO	-	-	-	-	-	-	-	-
Washing	IKE824F255	Motion Sensor Faucet	2.4	NO	-	2.4	NO	-	-	-	-	-	-	-	-
Washing	IKE824F257	Motion Sensor Faucet	1.5	NO	-	2.3	NO	-	-	-	-	-	-	-	-
Washing	IKE824F258	Motion Sensor Faucet	2.7	NO	-	5.3	NO	-	-	-	-	-	-	-	-
Washing	IKE824F259	Motion Sensor Faucet	1.5	NO	-	1.9	NO	-	-	-	-	-	-	-	-
Washing	IKE824F260	Motion Sensor Faucet	2	NO	-	2.1	NO	-	-	-	-	-	-	-	-
Washing	IKE824F261	Motion Sensor Faucet	1.4	NO	-	2.3	NO	-	-	-	-	-	-	-	-
Washing	IKE824F262	Motion Sensor Faucet	5.8	NO	-	6.9	NO	-	-	-	-	-	-	-	-
Washing	IKE824F256	Motion Sensor Faucet	2.1	NO	-	2.6	NO	-	-	-	-	-	-	-	-
Washing	IKE824F263	Motion Sensor Faucet	1.3	NO	-	2.3	NO	-	-	-	-	-	-	-	-
Washing	IKE824F264	Motion Sensor Faucet	0.92	NO	-	1.2	NO	-	-	-	-	-	-	-	-
Washing	IKE824F111	Motion Sensor Faucet	1.1	NO	-	2.6	NO	-	-	-	-	-	-	-	-
Washing	IKE824F103	Motion Sensor Faucet	non-detect	NO	-	38	YES	8/25/2017	NA	9.1	1.6	Replaced faucet	6.7	0.7	-

SAMPLE LOCATION DESCRIPTION			INITIAL FULL BUILDING SAMPLING RESULTS			SECOND FULL BUILDING SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS		
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 20ppb									Description	Recommended Level = 20ppb		
			First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush Collected 30 seconds after First Draw Sampling (ppb)		First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	
Washing	IKE824F265	Motion Sensor Faucet	non-detect	NO	-	0.53	NO	-	-	-	-	-	-	-	-
Washing	IKE824F266	Motion Sensor Faucet	non-detect	NO	-	3.5	NO	-	-	-	-	-	-	-	-
Washing	IKE824F267	Motion Sensor Faucet	non-detect	NO	-	1.4	NO	-	-	-	-	-	-	-	-
Washing	IKE824F268	Motion Sensor Faucet	non-detect	NO	-	4.1	NO	-	-	-	-	-	-	-	-
Washing	IKE824F269	Motion Sensor Faucet	non-detect	NO	-	2	NO	-	-	-	-	-	-	-	-
Washing	IKE824F270	Motion Sensor Faucet	8.7	NO	-	5.5	NO	-	-	-	-	-	-	-	-
Washing	IKE824F271	Motion Sensor Faucet	non-detect	NO	-	1.2	NO	-	-	-	-	-	-	-	-
Washing	IKE824F273	Motion Sensor Faucet	non-detect	NO	-	1.7	NO	-	-	-	-	-	-	-	-
Washing	IKE824F274	Motion Sensor Faucet	2.6	NO	-	10	NO	-	-	-	-	-	-	-	-
Washing	IKE824F272	Motion Sensor Faucet	8	NO	-	8.6	NO	-	-	-	-	-	-	-	-
Washing	IKE824F275	Motion Sensor Faucet	non-detect	NO	-	1	NO	-	-	-	-	-	-	-	-
Washing	IKE824F276	Motion Sensor Faucet	non-detect	NO	-	1.9	NO	-	-	-	-	-	-	-	-
Washing	IKE824F277	Motion Sensor Faucet	non-detect	NO	-	1.8	NO	-	-	-	-	-	-	-	-
Washing	IKE824F278	Motion Sensor Faucet	non-detect	NO	-	0.63	NO	-	-	-	-	-	-	-	-
Washing	IKE824F279	Motion Sensor Faucet	0.92	NO	-	2.2	NO	-	-	-	-	-	-	-	-
Washing	IKE824F280	Motion Sensor Faucet	1.1	NO	-	2.2	NO	-	-	-	-	-	-	-	-
Washing	IKE824F281	Motion Sensor Faucet	2	NO	-	1.3	NO	-	-	-	-	-	-	-	-
Washing	IKE824F282	Motion Sensor Faucet	1.3	NO	-	1	NO	-	-	-	-	-	-	-	-
Washing	IKE824F124	Motion Sensor Faucet	0.82	NO	-	0.9	NO	-	-	-	-	-	-	-	-
Washing	IKE824F125	Motion Sensor Faucet	1.6	NO	-	1.8	NO	-	-	-	-	-	-	-	-
Washing	IKE824F283	Motion Sensor Faucet	non-detect	NO	-	0.85	NO	-	-	-	-	-	-	-	-
Washing	IKE824F284	Motion Sensor Faucet	2	NO	-	2.5	NO	-	-	-	-	-	-	-	-
Washing	IKE824F286	Motion Sensor Faucet	non-detect	NO	-	1.4	NO	-	-	-	-	-	-	-	-
Washing	IKE824F287	Motion Sensor Faucet	1.6	NO	-	1.7	NO	-	-	-	-	-	-	-	-
Washing	IKE824F288	Motion Sensor Faucet	1.8	NO	-	2.1	NO	-	-	-	-	-	-	-	-
Washing	IKE824F285	Motion Sensor Faucet	4.5	NO	-	7.9	NO	-	-	-	-	-	-	-	-
Washing	IKE824F289	Motion Sensor Faucet	1.3	NO	-	1.3	NO	-	-	-	-	-	-	-	-
Washing	IKE824F291	Motion Sensor Faucet	0.94	NO	-	1	NO	-	-	-	-	-	-	-	-
Washing	IKE824F292	Motion Sensor Faucet	1.3	NO	-	1.9	NO	-	-	-	-	-	-	-	-
Washing	IKE824F290	Motion Sensor Faucet	0.71	NO	-	1	NO	-	-	-	-	-	-	-	-
Washing	IKE824F293	Motion Sensor Faucet	1.7	NO	-	1	NO	-	-	-	-	-	-	-	-
Washing	IKE824F294	Motion Sensor Faucet	12	NO	-	17	NO	-	-	-	-	-	-	-	-
Washing	IKE824F295	Motion Sensor Faucet	11	NO	-	20	YES	8/25/2017	NA	17	0.54	Replaced faucet	5.7	3.3	-

Notes:

¹ Faucets that were unsecured were permitted for handwashing and dishwashing use per BUMED concurrence. Kitchen faucet F62 was physically secured upon notification of exceedance on 5/5/2017, however the faucet was not used by kitchen staff as of 4/10/2017

² Second full building sampling excluded fixtures that were scheduled for replacement.

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS	SECOND SAMPLING RESULTS	RE-SAMPLING RESULTS			POST REMEDIATION RESULTS	
	First Draw (ppb)	First Draw (ppb)	Water Fountain Follow up Flush	First Draw (ppb)	Follow up Flush - Collected 30	First Draw (ppb)	Follow up Flush - Collected 30
Total Drinking	87	65	2	9	9	27	10
Total Drinking > 20 ppb	9	0	0	3	0	0	0
Total Cooking/Brushing	8	6	0	2	2	3	2
Total Cooking/Brushing > 20 ppb	2	0	0	1	0	0	0
Total Washing	149	144	0	5	5	10	10
Total Washing > 20 ppb	1	4	0	2	0	0	0
Total Samples	244	215	2	16	16	40	22
Total Samples > 20 ppb	12	4	0	6	0	0	0