

Priority Areas Lead Testing and Corrective Actions (December 2014)
JFK Child Development Center (Building 1376)

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)		Recommended Level = 20ppb	
Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)							First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	
SAMPLING DATE			12/3/2014			mm/dd/yyyy	12/12/2014	12/12/2014		mm/dd/yyyy	
RESULTS DATE			12/10/2014			mm/dd/yyyy	12/16/2014	12/16/2014		mm/dd/yyyy	
DRINKING	NP-B1376-RM113-WFB-FD	Room 113 Bubbler	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
DRINKING	NP-B1376-RM114-WFB-FD	Room 114 Bubbler	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
DRINKING	NP-B1376-RM115-WFB-FD	Room 115 Bubbler	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
DRINKING	NP-B1376-RM112-WFB-FD	Room 112 Bubbler	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
DRINKING	NP-B1376-RM116-WFB-FD	Room 116 Bubbler	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
DRINKING	NP-B1376-RM110-WFB-FD	Room 110 Bubbler	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
DRINKING	NP-B1376-RM117-WFB-FD	Room 117 Bubbler	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
DRINKING	NP-B1376-LOB-WFB(A)-FD	Lobby bubbler (left)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
DRINKING	NP-B1376-LOB-WFB(B)-FD	Lobby Bubbler (right)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
DRINKING	NP-B1376-RM125-WCB-FD	Room 125 Bubbler	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
DRINKING	NP-B1376-RM127-LHW(C)-FD	Room 127 Bubbler	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
COOKING/TEETH BRUSHING	NP-B1376-RM125-LHW(E)-FD	Room 125 faucet (food prep sink)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
COOKING	NP-B1376-RM105-LHW(B)-FD	Room 105 faucet (food prep, high)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
DISH WASHING - Broken & missing faucet should not have been sampled.	NP-B1376-RM128-LHW(A)-FD	Room 128 kitchen out of service, broken faucet	26	Yes	N/A	N/A	38	4	The faucet was broken off of the fixture in order to clean large pots. The faucet was replaced with a lead free fixture and it will be tested approximately 6 months after the installation.	N/A	N/A
COOKING	NP-B1376-RM128-LHW(B)-FD	Room 128 kitchen dishwashing faucet (left)	ND	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
COOKING	NP-B1376-RM128-LHW(C)-FD	Room 128 kitchen dishwashing faucet (right)	ND	No	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM113-LHW(A)-FD	Room 113 Faucet (left)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING - Hot water only tap should not have been sampled.	NP-B1376-RM113-LHW(B)-FD	Room 113 Faucet (right) - Hot Water Faucet	26	YES	N/A	N/A	80	ND	The USEPA Guidance, the 3Ts for Reducing Lead in Drinking Water, and Rhode Island's Lead Poison Prevention Regulation specifies sampling and testing of only the cold water tap because only flushed cold water is supposed to be used for cooking and drinking. Hot water is likely to contain greater amounts of lead. Since this fixture does not have a cold water tap it should not have been tested. The faucet was replaced with a lead free fixture.	N/A	N/A
HAND WASHING	NP-B1376-RM113-LHW(C)-FD	Room 113 Faucet (left, deep sink)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A

Priority Areas Lead Testing and Corrective Actions (December 2014)
JFK Child Development Center (Building 1376)

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Recommended Level = 20ppb			Description	Recommended Level = 20ppb	
						Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)		First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			12/3/2014			mm/dd/yyyy	12/12/2014	12/12/2014		mm/dd/yyyy	
RESULTS DATE			12/10/2014			mm/dd/yyyy	12/16/2014	12/16/2014		mm/dd/yyyy	
HAND WASHING	NP-B1376-RM113-LHW(D)-FD	Room 113 Faucet (right, deep sink)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM114-LHW(A)-FD	Room 114 bathroom faucet (left)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM114-LHN(B)-FD	Room 114 bathroom faucet (right)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM114-LHW(C)-FD	Room 114 faucet (deep sink, left)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM114-HHW-FD	Room 114 faucet (deep sink, right)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM115-LHW(A)-FD	Room 115 bathroom sink (left)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM115-LHW(B)-FD	Room 115 Bathroom sink (right)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM115-LHW(C)-FD	Room 115 Bubblers Sink	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM115-HHW-FD	Room 115 Faucet (near bubbler sink)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM112-LHW(B)-FD	Room 112 Bathroom Faucet (left)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM112-LHW(C)-FD	Room 112 Bathroom Faucet (right)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM112-LHW(D)-FD	Room 112 Faucet Bubbler Sink	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM112-HHW-FD	Room 112 Faucet Sink Near Bubbler	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM116-LHW(A)-FD	Room 116 Bathroom Faucet (left)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM116-LHW(B)-FD	Room 116 Bathroom Faucet (right)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM116-LHW(C)-FD	Room 116 Faucet (low sink)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM116-HHW-FD	Room 116 faucet (high sink)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM110-LHW(B)-FD	Room 110 faucet (left)	1	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM110-LHW(C)-FD	Room 110 faucet (right)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM110-HHW(A)-FD	Room 110 Faucet (left)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM110-HHW(B)-FD	Room 110 Faucet (right)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM117-LHW(B)-FD	Room 117 Faucet (right)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM117-LHW(C)-FD	Room 117 Faucet (low sink with bubbler)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM117-HHW-FD	Room 117 Faucet (high sink)	5	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM111A-UT-FD	Room 111A	1	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A

Priority Areas Lead Testing and Corrective Actions (December 2014)
JFK Child Development Center (Building 1376)

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Recommended Level = 20ppb				Description	First Draw (ppb) (See note 2)
						Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)			
SAMPLING DATE			12/3/2014			mm/dd/yyyy	12/12/2014	12/12/2014			mm/dd/yyyy
RESULTS DATE			12/10/2014			mm/dd/yyyy	12/16/2014	12/16/2014			mm/dd/yyyy
HAND WASHING	NP-B1376-LOBBATHWEST-LHW(A)-FD	Lobby west restroom faucet (left)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-LOBBATHWEST-LHW(B)-FD	Lobby west restroom faucet (right)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-LOBBATHWEST-LHW(A)-FD	Lobby east restroom faucet (left)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-LOBBATHWEST-LHW(B)-FD	Lobby east restroom faucet (right)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM107-HHW-FD	Room 107 Faucet	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM106-LHW(A)-FD	Room 106 Faucet (low)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM106-LHW(B)-FD	Room 106 faucet (high)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM125-LHW(A)-FD	Room 125 faucet (low, left)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM125-LHW(B)-FD	Room 125 faucet (low, right)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM125LHW(C)-FD	Room 125 (high, changing table)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM125-LHW(D)-FD	Room 125 Faucet (high goose neck)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM125-HHW-FD	Room 125 Faucet (low sink, no handle)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM105-LHW(A)-FD	Room 105 Faucet (low)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-Rm104-LHW(B)-FD	Room 104 Bathroom Faucet (left)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING - Hot water only tap should not have been sampled.	NP-B1376-RM104-HHW-FD	Room 104 Bathroom Hot Water Faucet (right)	119	YES	N/A	N/A	3	ND	The USEPA Guidance, the 3Ts for Reducing Lead in Drinking Water, and Rhode Island's Lead Poison Prevention Regulation specifies sampling and testing of only the cold water tap because only flushed cold water is supposed to be used for cooking and drinking. Hot water is likely to contain greater amounts of lead. Since this fixture does not have a cold water tap it should not have been tested. The faucet was replaced with a lead free fixture.	N/A	N/A
HAND WASHING	NP-B1376-RM127-LHW(A)-FD	Room 127 Faucet (push button, right)	3	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM127-LHW(B)-FD	Room 127 Faucet (push button, left)	3	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM127-HHW-FD	Room 127 Faucet (Deep Sink)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM103-LHW(A)-FD	Room 103 Faucet (low)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM103-LHW(B)-FD	Room 103 Faucet (high)	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A

Priority Areas Lead Testing and Corrective Actions (December 2014)
JFK Child Development Center (Building 1376)

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 20ppb				First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)				Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb) (See note 2)		
SAMPLING DATE			12/3/2014			mm/dd/yyyy	12/12/2014	12/12/2014		mm/dd/yyyy	
RESULTS DATE			12/10/2014			mm/dd/yyyy	12/16/2014	12/16/2014		mm/dd/yyyy	
HAND WASHING - Hot water only tap should not have been sampled.	NP-B1376-RM102-LHW(A)-FD	Room 102 hot water faucet	26	Yes	N/A	N/A	836	5	The USEPA Guidance, the 3Ts for Reducing Lead in Drinking Water, and Rhode Island's Lead Poison Prevention Regulation specifies sampling and testing of only the cold water tap because only flushed cold water is supposed to be used for cooking and drinking. Hot water is likely to contain greater amounts of lead. Since this fixture does not have a cold water tap it should not have been tested. The faucet was replaced with a lead free fixture.	N/A	N/A
HAND WASHING	NP-B1376-RM102-HHW(B)-FD	Room 102 faucet	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING	NP-B1376-RM102-UTRM130-UT-FD	Laundry Room	non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A
HAND WASHING			non-detect	NO	N/A	N/A	N/A	N/A	Aerators Replaced in July 2014 and will undergo regular preventative cleaning.	N/A	N/A

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS		RE-SAMPLING RESULTS		POST REMEDIATION RESULTS
	Recommended Level = 20ppb		Recommended Level = 20ppb		
	First Draw (ppb)	Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb)
Total Drinking	11	N/A	0	0	0
Total Drinking > 20 ppb	0	N/A	0	0	0
Total Cooking / Brushing Teeth	4	N/A	1	1	0
Total Cooking /Brushing Teeth > 20 ppb	1	N/A	1	0	0
Total Hand Washing	52	N/A	3	3	0
Total Hand Washing > 20 ppb	3	N/A	2	0	0
Total Samples	67	N/A	4	4	0
Total Samples > 20 ppb	4	N/A	3	0	0