

The United States Navy (Navy) has conducted a National Environmental Policy Act review to analyze the potential environmental impacts that could result from the construction of base-wide security improvements at NAS JRB Fort Worth.

Part of the improvements include a new vehicle inspection area and watch tower to be located just inside the NAS JRB Fort Worth East Gate, and a new perimeter fence along the border with Bureau of Prisons property; this new construction is within the 100-year floodplain. In accordance with Executive Order 11988, Floodplain Management, the Navy is making the above aspects of this project available for public review and comment.

Written comments will be received and considered for 30 days from the date of this publication and should be directed to Ms. Candateshia Pafford, Public Affairs Officer, 1510 Chennault Ave, NAS JRB Fort Worth TX 76127 via email at [candateshia.pafford@navy.mil](mailto:candateshia.pafford@navy.mil).

# Naval Air Station Joint Reserve Base Fort Worth, TXP100U, Security Improvements

- Multiple security improvements at key entry control points (ECP) and other segments of installation perimeter. At Bureau of Prisons area, install 1,800 LF of fencing, a roadway swing gate, and perimeter lights. At the East Gate, construct a vehicle inspection area, an overwatch tower, and guardhouse canopy. According to UFC 4-022-01, the ECPs and perimeter fencing act as a physical barrier to prevent access to the installation by unauthorized personnel. All security improvements listed here are required by UFC to achieve sufficient security for the installation.

