

Priority Areas Lead Testing and Corrective Actions December 2014
NS Guantanamo Bay Child Development Center BLDG 1681

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Recommended Level = 20ppb				First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
Category Water Intended For:	Sample ID	Outlet Description				mm/dd/yyyy	1/11/2015	1/11/2015	mm/dd/yyyy		
SAMPLING DATE			12/7/2014			mm/dd/yyyy	1/11/2015	1/11/2015		mm/dd/yyyy	
RESULTS DATE			12/17/2014			mm/dd/yyyy	1/21/2015	1/21/2015		mm/dd/yyyy	
DRINKING	GTMO-1681-B5-RM-WFCOMB-FD (BLDG 1681-2-C)	Classroom used for daycare - lowered water fountain sharing sink with hand wash faucet	57	YES	N/A	N/A	61	8.8	Routine Control Measures Only - Outlet removed from service	N/A	N/A
DRINKING	GTMO-1681-B7-RM-WFCOMB-FD (BLDG 1681-4-C)	Classroom used for daycare - lowered water fountain sharing sink with hand wash faucet	2.5	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	GTMO-1681-B9-RM-WFCOMB-FD (BLDG 1681-8-C)	Classroom used for daycare - lowered water fountain sharing sink with hand wash faucet	110	YES	N/A	N/A	140	12	Routine Control Measures Only - Outlet removed from service	N/A	N/A
DRINKING	GTMO-1681-B11-RM-WFCOMB-FD (BLDG 1681-10-C)	Classroom used for daycare - lowered water fountain sharing sink with hand wash faucet	8	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	GTMO-1681-B13-RM-WFCOMB-FD (BLDG 1681-14-C)	Classroom used for daycare - lowered water fountain sharing sink with hand wash faucet	180	YES	N/A	N/A	750	1.5	Routine Control Measures Only - Outlet removed from service	N/A	N/A
DRINKING	GTMO-1681-B15-RM-WFCOMB-FD (BLDG 1681-16-C)	Classroom used for daycare - lowered water fountain sharing sink with hand wash faucet	78	YES	N/A	N/A	23	4.9	Routine Control Measures Only - Outlet removed from service	N/A	N/A
DRINKING	GTMO-1681--LOUNGE-WFCOMB-FD (BLDG 1681-19-C)	CDC Breakroom/Lounge - lowered water fountain sharing sink with hand wash faucet	190	YES	N/A	N/A	150	15	Routine Control Measures Only - Outlet removed from service	N/A	N/A
WASHING	GTMO-1681-B5-RM-HWCOMB-FD (BLDG 1681-1-C)	Classroom used for daycare - lowered hand wash faucet sharing sink with water fountain	52	YES	N/A	N/A	13	2	Routine Control Measures Only	N/A	N/A
WASHING	GTMO-1681-B7-RM-HWCOMB-FD (BLDG 1681-3-C)	Classroom used for daycare - lowered hand wash faucet sharing sink with water fountain	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	GTMO-1681-B7-RM-LHWA-FD (BLDG 1681-5-C)	Classroom used for daycare - low hand wash sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions December 2014
NS Guantanamo Bay Child Development Center BLDG 1681

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)		Recommended Level = 20ppb	
Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)							Description	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			12/7/2014			mm/dd/yyyy	1/11/2015	1/11/2015		mm/dd/yyyy	
RESULTS DATE			12/17/2014			mm/dd/yyyy	1/16/2015	1/16/2015		mm/dd/yyyy	
WASHING	GTMO-1681-B7-RM-LHWP-FD (BLDG 1681-6-C)	Classroom used for daycare - low hand wash sink	1.5	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	GTMO-1681-B9-RM-HWCOMB-FD (BLDG 1681-7-C)	Classroom used for daycare - lowered hand wash faucet sharing sink with water fountain	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	GTMO-1681-B11-RM-HWCOMB-FD (BLDG 1681-9-C)	Classroom used for daycare - lowered hand wash faucet sharing sink with water fountain	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	GTMO-1681-B11-RM-LHWA-FD (BLDG 1681-11-C)	Classroom used for daycare - low hand wash sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	GTMO-1681-B11-RM-LHWP-FD (BLDG 1681-12-C)	Classroom used for daycare - low hand wash sink	2.9	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	GTMO-1681-B13-RM-HWCOMB-FD (BLDG 1681-13-C)	Classroom used for daycare - lowered hand wash faucet sharing sink with water fountain	1.9	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	GTMO-1681-B15-RM-HWCOMB-FD (BLDG 1681-15-C)	Classroom used for daycare - lowered hand wash faucet sharing sink with water fountain	1.6	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	GTMO-1681-B15-RM-LHW-FD (BLDG 1681-17-C)	Classroom used for daycare - low hand wash sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	GTMO-1681--LOUNGE-HWCOMB-FD (BLDG 1681-18-C)	CDC Breakroom/Lounge - lowered hand wash faucet sharing sink with water fountain	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Notes:
¹ Affected outlets were immediately secured after receiving verbal communication from the lab on results exceeding the recommended level of 20ppb.

Priority Areas Lead Testing and Corrective Actions December 2014
NS Guantanamo Bay Child Development Center BLDG 1681

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS	RE-SAMPLING RESULTS			POST REMEDIATION RESULTS
	Recommended Level = 20ppb				
	First Draw (ppb)	Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb)
Total Drinking	7	0	5	5	0
Total Drinking > 20 ppb	5	0	5	0	0
Total Cook/Brush	0	0	0	0	0
Total Cook/Brush > 20 ppb	0	0	0	0	0
Total Washing	12	0	1	1	0
Total Washing > 20 ppb	1	0	0	0	0
Total Samples	19	0	6	6	0
Total Samples > 20 ppb	6	0	5	0	0