

Priority Areas Lead Testing and Corrective Actions June 2019
 NASJRB New Orleans Play Areas Building 571, 39, Plaquedilla Park, Swimming Pool

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 15 ppb							Recommended Level = 15 ppb	
			First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			6/8/2019			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
RESULTS DATE			6/20/2019			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
DRINKING	NOLA-571-PLAY-WFB-A-FD (OPA-1)	Covered Pavilion in Sports Complex (571) - Bubbler fountain situated higher	2.7	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	NOLA-571-PLAY-WFB-B-FD (OPA-2)	Covered Pavilion in Sports Complex (571) - Bubbler fountain situated lower	6.5	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	NOLA-571-WFC-A-FD (OPA-3)	Fountain outside restroom building in Sports Complex (571) - Cooler fountain	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	NOLA-571-WFC-B-FD (OPA-4)	Fountain outside restroom building in Sports Complex (571) - Cooler fountain	1.3	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	NOLA-39-PLAY-WFC-A-FD (OPA-6)	Plaquedilla Park Restroom Bldg. (39). Fountain on the left	3.4	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	NOLA-39-PLAY-WFC-B-FD (OPA-7)	Plaquedilla Park Restroom Bldg. (39) . Fountain on the right	3.8	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	NOLA-39-PLAY-BOTTLE-FD (OPA-8)	Plaquedilla Park Restroom Bldg. (39) , Bottle Filling Station		NO	N/A	N/A	N/A	N/A	Inoperable	N/A	N/A

Priority Areas Lead Testing and Corrective Actions June 2019
 NASJRB New Orleans Play Areas Building 571, 39, Plaquedilla Park, Swimming Pool

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 15 ppb					
First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)				Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			6/8/2019			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
RESULTS DATE			6/20/2019			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
DRINKING	NOLA-OUTDOOR-PLAY-WFB-A-FD (OPA-9)	Plaquedilla Park Playground , Faucet situated lower	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	NOLA-OUTDOOR-PLAY-WFB-B-FD (OPA-10)	Plaquedilla Park Playground , Faucet situated higher	1.4	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	NOLA-OUTDOOR-PLAY-HOSE-FD (OPA-11)	Plaquedilla Park Playground, Hose attachment connected to fountains A and B	2	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	NOLA-409-PLAY-WFC-A&B-FD (OPA-12)	Swimming Pool , Fountain on the left	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	NOLA-409-PLAY-WFC-A&B-FD (OPA-13)	Swimming Pool , Fountain on the right	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	NOLA-39-K-FD (OPA-5)	Plaquedilla Park Restroom Bldg. (39) - Steel sink outside restroom building	1.7	NO	N/A	N/A	N/A	N/A		N/A	N/A

Notes:

¹ Affected outlets were immediately secured after receiving verbal communication from the lab on results exceeding the recommended level of 15 ppb.

² Post-remediation sampling was initially conducted on N/A. Additional N/A were implemented and final results below recommended level of 15 ppb for sample collected on N/A are shown on the table.

Priority Areas Lead Testing and Corrective Actions June 2019
 NASJRB New Orleans Play Areas Building 571, 39, Plaquedilla Park, Swimming Pool

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 15 ppb							Recommended Level = 15 ppb	
			First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			6/8/2019			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
RESULTS DATE			6/20/2019			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS	RE-SAMPLING RESULTS			POST REMEDIATION RESULTS
	Recommended Level = 15 ppb				
	First Draw (ppb)	Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb)
Total Drinking	11	0	0	0	0
Total Drinking > 15 ppb	0	0	0	0	0
Total Cook/Brush	1	0	0	0	0
Total Cook/Brush > 15 ppb	0	0	0	0	0
Total Washing	0	0	0	0	0
Total Washing > 15 ppb	0	0	0	0	0
Total Samples	12	0	0	0	0
Total Samples > 15 ppb	0	0	0	0	0