

Priority Areas Lead Testing and Corrective Actions May 2018  
Naval Air Station Mayport Youth Center Building 2084

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Recommended Level = 20ppb				Description	Recommended Level = 20ppb
						Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb) (See note 2)		Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			5/5/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
RESULTS DATE			5/30/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
DRINKING	MYP-2084-HALL-WFC-A-FD (BLDG 2084-4)	Between room 105 and 106	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MYP-2084-HALL-WFC-B-FD (BLDG 2084-5)	Between room 105 and 106	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MYP-2084-RM107-RM-WFB- FD (BLDG 2084-11)	Purple Room	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MYP-2084-RM108-RM-WFB- FD (BLDG 2084-13)	Orange Room	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MYP-2084-RM109-RM-WFB- FD (BLDG 2084-17)	Green Room	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MYP-2084-RM110-RM-WFB- FD (BLDG 2084-20)	Red Room	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MYP-2084-RM115-RM-WFD- FD (BLDG 2084-23)	Yellow Room	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MYP-2084-PLAY-WFB-A-FD (BLDG 2084-24)	Outside play area Near basketball court/Next to AC unit	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MYP-2084-PLAY-WFBA-B-FD (BLDG 2084-25)	Outside play area Near basketball court/Next to AC unit	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	MYP-2084-RM117-K-HHW-FD (BLDG 2084-26)	Kitchen	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	MYP-2084-RM119-LOUNGE-K- FD (BLDG 2084-28)	Teachers Lounge Food Preparation	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-2084-RM105-BATH-HHW- A-FD (BLDG 2084-1)	Hallway Girls bath room	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-2084-RM105-BATH-HHW- B-FD (BLDG 2084-2)	Hallway Girls bath room	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-2084-RM105-BATH-HHW- C-FD (BLDG 2084-3)	Hallway Girls bath room, Handicap stall	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions May 2018  
Naval Air Station Mayport Youth Center Building 2084

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 20ppb							Recommended Level = 20ppb	
			First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			5/5/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
RESULTS DATE			5/30/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
WASHING	MYP-2084-RM106-BATH-HHW-A-FD (BLDG 2084-6)	Hallway Boys bathroom, Handicap Stall	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-2084-RM106-BATH-HHW-B-FD (BLDG 2084-7)	Hallway Boys bathroom	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-2084-RM106-BATH-HHW-C-FD (BLDG 2084-8)	Hallway Boys bathroom	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-2084-RM107-RM-HHW-A-FD (BLDG 2084-9)	Purple Room	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-2084-RM107-RM-HHW-B-FD (BLDG 2084-10)	Purple Room	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-2084-RM108-RM-HHWA-FD (BLDG 2084-12)	Orange Room	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-2084-RM108-RM-HHW-B-FD (BLDG 2084-14)	Orange Room Sink with no fountain	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-2084-RM109-RM-HHW-A-FD (BLDG 2084-15)	Green Room	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-2084-RM109-RM-HHW-B-FD (BLDG 2084-16)	Green Room Sink with fountain	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-2084-RM110-RM-HHW-A-FD (BLDG 2084-18)	Red Room Sink with fountain	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-2084-RM110-RM-HHW-B-FD (BLDG 2084-19)	Red Room	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-2084-RM115-RM-HHW-A-FD (BLDG 2084-21)	Yellow Room	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-2084-RM115-HHWB-FD (BLDG 2084-22)	Yellow Room Sink with fountain	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-2084-RM118-BATH-HHW-FD (BLDG 2084-29)	Staff Restroom	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Notes:

<sup>1</sup> Affected outlets were immediately secured after receiving verbal communication from the lab on results exceeding the recommended level of 20ppb.

<sup>2</sup> Post-remediation sampling was initially conducted on N/A. Additional N/A were implemented and final results below recommended level of 20ppb for sample collected on N/A are shown on the table.

Priority Areas Lead Testing and Corrective Actions May 2018  
Naval Air Station Mayport Youth Center Building 2084

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 20ppb			First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description		Recommended Level = 20ppb	
			First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)				Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			5/5/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
RESULTS DATE			5/30/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS	RE-SAMPLING RESULTS			POST REMEDIATION RESULTS
	Recommended Level = 20ppb				
	First Draw (ppb)	Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb)
Total Drinking	9	0	0	0	0
Total Drinking > 20 ppb	0	0	0	0	0
Total Cook/Brush	2	0	0	0	0
Total Cook/Brush > 20 ppb	0	0	0	0	0
Total Washing	17	0	0	0	0
Total Washing > 20 ppb	0	0	0	0	0
Total Samples	28	0	0	0	0
Total Samples > 20 ppb	0	0	0	0	0