



NSA Naples Radon Study Results

Site	Facility #	Building Name	Room	Detector 1 pCi/L	Detector 2 pCi/L	Average pCi/L	Mitigation Required by
Capodichino	403	FIRE/SECURITY BLDG.	30 PHYSICAL SECURITY	34.3	36.9	35.6	6 months
Capodichino	411A	WEST GATE SENTRY TOWER	MAIN	4.7	4.8	4.8	2 Years
Capodichino	468	PASS & ID at EAST GATE	GATE HOUSE	28.0	30.0	29.0	6 months
Carney Park	528	BATH HOUSE/SWIM POOL	POOL OFFICE	17.2	18.8	18.0	2 Years
GAETA	725	TENDER TRANSIT SHED	OFFICE 1	4.7	5.3	5.0	2 Years
GAETA	752A	LAUNDRY/BARBER-BEAUTY SALON	BARBER	5.4	5.5	5.5	2 Years
GAETA	752A	LAUNDRY/BARBER-BEAUTY SALON	LAUNDRY	4.9	6.3	5.6	2 Years
OLDE MILL INN	707	EM MESS OPEN	CHAMPS	5.8	5.6	5.7	2 Years
OLDE MILL INN	707	EM MESS OPEN	CHILD PLAY AREA OFF DINNING	8.5	7.3	7.9	2 Years
OLDE MILL INN	707	EM MESS OPEN	DINNING RM	6.7	7.3	7.0	2 Years
OLDE MILL INN	707	EM MESS OPEN	KITCHEN	5.0	4.6	4.8	2 Years
LAGO PATRIA	103	SATCOM TERM SUPPORT BLDG	OFF 1 ACROSS FR MALE LCKR	5.6	5.6	5.6	2 Years
LAGO PATRIA	103	SATCOM TERM SUPPORT BLDG	OFF 2 ACROSS FR MALE LCKR	6.2	6.3	6.3	2 Years
LAGO PATRIA	103	SATCOM TERM SUPPORT BLDG	OFF 2 OFF BREAK RM	4.8	4.5	4.7	2 Years
LAGO PATRIA	103	SATCOM TERM SUPPORT BLDG	SATCOM DEPT OFFICE	5.8	5.4	5.6	2 Years
LAGO PATRIA	103	SATCOM TERM SUPPORT BLDG	STORAGE	8.2	8.2	8.2	2 Years
Support Site *	2057	ELEMENTARY SCHOOL	137 MPR STRG BK	6.0	5.8	5.9	2 Years
Support Site	2074	FAMILY HOUSING OFFICES	SERVICES HELP M07	6.6	6.6	6.6	2 Years
Support Site	2078	MWR WAREHOUSE	R2	7.8	6.7	7.3	2 Years
Support Site	2078	MWR WAREHOUSE	R3	18.5	18.8	18.7	2 Years
Support Site	2078	MWR WAREHOUSE	R4 INVENTORY CTR	4.3	4.9	4.6	2 Years
Support Site	2078	MWR WAREHOUSE	R5 FAC MGR	17.5	19.4	18.5	2 Years
Support Site	2078	MWR WAREHOUSE	R6 BREAK	4.3	3.9	4.1	2 Years
Support Site	2091	EXCHANGE & RETAIL CENTER	THEATER 4.034 OFF & CON. STRG	5.4	5.2	5.3	2 Years