

Priority Areas Lead Testing and Corrective Actions NOVEMBER 2014
NAS PENSACOLA National Flight Academy Building 4191

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured?	Recommended Level = 20ppb				Description	Recommended Level = 20ppb
						Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb)		Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			10/18/2014			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
RESULTS DATE			10/29/2014			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
DRINKING	PNS-4191-1STFLOOR-HALL-WFC-A-FD (BLDG 4191-1)	First Floor Hall, Inside Of Mock-Up Water Fountain Cooler	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	PNS-4191-1STFLOOR-HALL-WFC-B-FD (BLDG 4191-2)	First Floor Hall Water Fountain Cooler	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	PNS-4191-1STFLOOR-HALL-WFC-C-FD (BLDG 4191-3)	First Floor Hall Water Fountain Cooler	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	PNS-4191-1STFLOOR-K-ICE-FD (BLDG 4191-4)	First Floor No Food Cooked, Ice Machine Only	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	PNS-4191-2NDFLOOR-HALL-WFC-A-FD (BLDG 4191-5)	See Frame Location Df-109-P Water Fountain Cooler	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	PNS-4191-2NDFLOOR-HALL-WFC-B-FD (BLDG 4191-6)	See Frame Location Df-109-P Water Fountain Cooler	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	PNS-4191-2NDFLOOR-HALL-WFC-C-FD (BLDG 4191-7)	See Frame Location Df-109-P Water Fountain Cooler	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	PNS-4191-2NDFLOOR-HALL-WFC-F-FD (BLDG 4191-10)	Fr 106 Next To First Class Mess Water Fountain Cooler	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	PNS-4191-2NDFLOOR-HALL-WFC-G-FD (BLDG 4191-11)	Fr 106 Next To First Class Mess Water Fountain Cooler	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	PNS-4191-3RDFLOOR-HALL-WFC-A-FD (BLDG 4191-12)	Central Hallway Water Fountain Cooler	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	PNS-4191-3RDFLOOR-HALL-WFC-B-FD (BLDG 4191-13)	Central Hallway Water Fountain Cooler	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	PNS-4191-3RDFLOOR-HALL-WFC-C-FD (BLDG 4191-14)	Central Hallway Water Fountain Cooler	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	PNS-4191-3RDFLOOR-HALL-WFC-D-FD (BLDG 4191-15)	By Comm Rm North 02-118-1-C Water Fountain Cooler	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	PNS-4191-3RDFLOOR-HALL-WFC-E-FD (BLDG 4191-16)	By Comm Rm North 02-118-1-C Water Fountain Cooler	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	PNS-4191-3RDFLOOR-HALL-WFC-F-FD (BLDG 4191-17)	Fr 301 Comm - 02-307-1-C Water Fountain Cooler	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	PNS-4191-3RDFLOOR-HALL-WFC-A-FD (BLDG 4191-18)	Fr 301 Comm - 02-307-1-C Water Fountain Cooler	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	PNS-4191-4THFLOOR-HALL-WFC-A-FD (BLDG 4191-19)	Central Hallway Water Fountain Cooler	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions NOVEMBER 2014
NAS PENSACOLA National Flight Academy Building 4191

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 20ppb							Recommended Level = 20ppb	
			First Draw (ppb)	Retest required?	Date Fixture Secured?	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			10/18/2014			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
RESULTS DATE			10/29/2014			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
DRINKING	PNS-4191-4THFLOOR-HALL-WFC-B-FD (BLDG 4191-20)	Central Hallway Water Fountain Cooler	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	PNS-4191-4THFLOOR-HALL-WFC-C-FD (BLDG 4191-21)	Central Hallway Water Fountain Cooler	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	PNS-4191-4THFLOOR-HALL-WFC-D-FD (BLDG 4191-22)	Northside Common Area Water Fountain Cooler	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	PNS-4191-4THFLOOR-HALL-WFC-E-FD (BLDG 4191-23)	Northside Common Area Water Fountain Cooler	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	PNS-4191-4THFLOOR-HALL-WFC-F-FD (BLDG 4191-24)	Southside Common Area Water Fountain Cooler	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	PNS-4191-4THFLOOR-HALL-WFC-A-FD (BLDG 4191-25)	Southside Common Area Water Fountain Cooler	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Notes:

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS	RE-SAMPLING RESULTS			POST REMEDIATION RESULTS
	Recommended Level = 20ppb				
	First Draw (ppb)	Water Fountain	First Draw (ppb)	Follow up Flush	First Draw (ppb)
Total Drinking	23	0	0	0	0
Total Drinking > 20 ppb					
	0	0	0	0	0
Total Cook/Brush	0	0	0	0	0
Total Cook/Brush > 20 ppb	0	0	0	0	0
Total Washing	0	0	0	0	0
Total Washing > 20 ppb	0	0	0	0	0
Total Samples	23	0	0	0	0
Total Samples > 20 ppb	0	0	0	0	0