

Priority Areas Lead Testing and Corrective Actions (OCT 2014)  
 NAS JACKSONVILLE Youth Center  
 Building 2069

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 20ppb							Recommended Level = 20ppb	
			First Draw (ppb) [Enter non-detect/ numeric value]	Retest required? [Enter YES/NO]	Date Fixture Secured? (See Note 1) [Enter mm/dd/yyyy]	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb) [Enter non-detect/ numeric value]	First Draw (ppb) [Enter non-detect/ numeric value]	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb) [Enter non-detect/ numeric value]	Description	First Draw (ppb) (See note 2) [Enter non-detect/ numeric value]	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb) [Enter non-detect/ numeric value]
SAMPLING DATE			10/11/2014			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
RESULTS DATE			10/26/2014			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
DRINKING	JAX-2069-HALL-WFCA-FD (BLDG 2069-1)	Fountain In Lobby High, on left	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	JAX-2069-HALL-WFCB-FD (BLDG 2069 -2)	Fountain In Lobby Low, on right	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	JAX 2069-K-K-FD (BLDG 2069-6)	Kitchen sink behind front desk - Break room	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069-BATHW-HHW-FD (BLDG 2069-3)	Lobby Rest Room Women Restroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069-BATHM-HHW-FD (BLDG 2069-4)	Lobby Rest Room Men Restroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069- BATH-M/W-HHW-FD (BLDG 2069-5)	Lobby - rest room sink across from front desk	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069-RM1-RM-HHW-FD (BLDG 2069-7)	First room on right Education, yellow room	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069-RM2-RM-HHW-FD (BLDG 2069-8)	Second room on right Art, blue room	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069-RM3-RM-HHW-FD (BLDG 2069-9)	Third room on right Science, Green room	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069-RM4-RM-HHW-FD (BLDG 2069-10)	First room on left Dramatic Play, teal room	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069-RM5-RM-HHW-FD (BLDG 2069-11)	Second room on left Manipulative, orange room	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Notes:

<sup>1</sup> Affected outlets were immediately secured after receiving verbal communication from the lab on results exceeding the recommended level of 20ppb.

<sup>2</sup> Post-remediation sampling was initially conducted on N/A. Additional N/A were implemented and final results below recommended level of 20ppb for sample collected on N/A are shown on the table.

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS	RE-SAMPLING RESULTS			POST REMEDIATION RESULTS
	Recommended Level = 20ppb				
	First Draw (ppb)	Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb)
<b>Total Drinking</b>	<b>2</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>

Priority Areas Lead Testing and Corrective Actions (OCT 2014)  
 NAS JACKSONVILLE Youth Center  
 Building 2069

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 20ppb							Description	Recommended Level = 20ppb
			First Draw (ppb) [Enter non-detect/numeric value]	Retest required? [Enter YES/NO]	Date Fixture Secured? (See Note 1) [Enter mm/dd/yyyy]	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb) [Enter non-detect/numeric value]	First Draw (ppb) [Enter non-detect/numeric value]	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb) [Enter non-detect/numeric value]	First Draw (ppb) (See note 2) [Enter non-detect/numeric value]		Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb) [Enter non-detect/numeric value]
<b>SAMPLING DATE</b>			10/11/2014			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
<b>RESULTS DATE</b>			10/26/2014			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
Total Drinking > 20 ppb		0	0		0		0		0		
Total Cook/Brush		1	0		0		0		0		
Total Cook/Brush > 20 ppb		0	0		0		0		0		
Total Washing		8	0		0		0		0		
Total Washing > 20 ppb		0	0		0		0		0		
Total Samples		11	0		0		0		0		
Total Samples > 20 ppb		0	0		0		0		0		