

Priority Areas Lead Testing and Corrective Actions (November 2014)  
NAS WHITING FIELD Child Development Center Building 36

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)		Recommended Level = 20ppb	
Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)							mm/dd/yyyy	12/15/2014	12/15/2014
SAMPLING DATE			11/18/2014				mm/dd/yyyy	12/15/2014	12/15/2014		
RESULTS DATE			11/25/2014				mm/dd/yyyy	12/17/2014	12/17/2014		
DRINKING	WF-36-RM103-RM-WFCOMB-FD (BLDG 36-7)	Pre Toddler Room - Low sink in back of room with fountain	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	WF-36-RM104-RM-WFCOMB-FD (BLDG 36-9)	Pre school Room - Low sink in back of room on left with fountain	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	WF-36-RM106-RM-WFCOMB-FD (BLDG 36-14)	Pre school Room - Low sink with fountain, in front of room near bathroom area	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	WF-36-RM110-RM-WFCOMB-FD (BLDG 36-19)	Office/Training Room - Near front of room, not used often, if used it is for handwashing only	3.5	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	WF-36-HALL-WFC-FD (BLDG 36-22)	Hallway - Water fountain in hallway between Room 110 and Room 115 Bathroom	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	WF-36-RM108-LOUNGE-K-FD (BLDG 36-2)	Teachers Lounge - Kitchen sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	WF-36-RM119-K-K-FD (BLDG 36-24)	Kitchen - Kitchen sink used for food prep and dishwashing, double stainless steel sink with one faucet	1.3	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	WF-36-RM119-K-HHW-FD (BLDG 36-25)	Kitchen - White handwashing sink on right side of kitchen	1.2	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	WF-36-RM107-NURSE-LHW-FD (BLDG 36-1)	Isolation Room - Children's sink only used when have sick child in isolation room	1.6	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	WF-36-RM103-RM-HHW-FD (BLDG 36-3)	Pre Toddler Room - Stainless steel sink near bathroom area	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	WF-36-RM103-RM-LHW-A-FD (BLDG 36-4)	Pre Toddler Room - Children's bathroom sink on left	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	WF-36-RM103-RM-LHW-B-FD (BLDG 36-5)	Pre Toddler Room - Children's bathroom sink on right	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	WF-36-RM103-RM-HWCOMB-FD (BLDG 36-6)	Pre Toddler Room - Low sink in back of room with fountain	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	WF-36-RM104-RM-HWCOMB-FD (BLDG 36-8)	Pre school Room - Low sink in back of room on left with fountain	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	WF-36-RM104-RM-LHW-A-FD (BLDG 36-11)	Pre school Room - Childs bathroom sink on left, also used for teethbrushing.	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	WF-36-RM104-RM-LHW-B-FD (BLDG 36-12)	Pre school Room - Children's bathroom sink on right, also used for teethbrushing.	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	WF-36-RM106-RM-HWCOMB-FD (BLDG 36-13)	Pre school Room - Low sink with fountain, in front of room near bathroom area	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions (November 2014)  
NAS WHITING FIELD Child Development Center Building 36

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS		
			CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)		Recommended Level = 20ppb		
Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)							mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy	
SAMPLING DATE			11/18/2014			mm/dd/yyyy	12/15/2014	12/15/2014			mm/dd/yyyy	
RESULTS DATE			11/25/2014			mm/dd/yyyy	12/17/2014	12/17/2014			mm/dd/yyyy	
WASHING	WF-36-RM106-RM-HHW-FD (BLDG 36-15)	Pre school Room - White sink in front of room near bathroom area	non-detect	NO	N/A	N/A	N/A	N/A			N/A	N/A
WASHING	WF-36-RM106-RM-LHW-A-FD (BLDG 36-16)	Pre school Room - Children's bathroom sink on left, also used for teethbrushing.	non-detect	NO	N/A	N/A	N/A	N/A			N/A	N/A
WASHING	WF-36-RM106-RM-LHW-B-FD (BLDG 36-17)	Pre school Room - Children's bathroom sink on left, also used for teethbrushing	non-detect	NO	N/A	N/A	N/A	N/A			N/A	N/A
WASHING	WF-36-RM110-RM-HWCOMB-FD (BLDG 36-18)	Office/Training Room - Near front of room, not used often, if used it is for handwashing only	12	NO	N/A	N/A	N/A	N/A			N/A	N/A
WASHING	WF-36-RM110-RM-HHW-FD (BLDG 36-20)	Office/Training Room - In back of room, used for handwashing only, is used at all	12	NO	N/A	N/A	N/A	N/A			N/A	N/A
WASHING	WF-36-HALL-BATH-HHW-FD (BLDG 36-21)	Hallway - Bathroom across hall from Room 110, no room number marked	non-detect	NO	N/A	N/A	N/A	N/A			N/A	N/A
WASHING	WF-36-RM115-BATH-HHW-FD (BLDG 36-23)	Hallway - Bathroom in hall on left, marked as Room 115	non-detect	NO	N/A	N/A	N/A	N/A			N/A	N/A
WASHING	WF-RM116-RM-HHW-A-FD (BLDG 36-27)	Infants Room - First handwashing sink on left side of room, sink on the left	1.4	NO	N/A	N/A	N/A	N/A			N/A	N/A
WASHING	WF-RM116-RM-HHW-B-FD (BLDG 36-28)	Infants Room - Second handwashing sink on left side of room, sink on the right.	non-detect	NO	N/A	N/A	N/A	N/A			N/A	N/A
WASHING	WF-36-RM110-LHWA-FD (BLDG 36-29)	Low hand washing faucet (intended for toddler access)	22	YES	N/A	N/A	non-detect	non-detect	Routine Control Measures Only		N/A	N/A
WASHING	WF-36- (BLDG 36-30)		3	NO	N/A	N/A	N/A	N/A			N/A	N/A

Notes:  
<sup>1</sup> Affected outlets were immediately secured after receiving verbal communication from the lab on results exceeding the recommended level of 20ppb.

Priority Areas Lead Testing and Corrective Actions (November 2014)  
 NAS WHITING FIELD Child Development Center Building 36

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS	RE-SAMPLING RESULTS			POST REMEDIATION RESULTS
	First Draw (ppb)	Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	Recommended Level = 20ppb		First Draw (ppb)
			First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	
Total Drinking	5	0	0	0	0
Total Drinking > 20 ppb	0	0	0	0	0
Total Cook/Brush	3	0	0	0	0
Total Cook/Brush > 20 ppb	0	0	0	0	0
Total Washing	20	0	1	1	0
Total Washing > 20 ppb	1	0	0	0	0
Total Samples	28	0	1	1	0
Total Samples > 20 ppb	1	0	0	0	0